



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS FSI
Colour	Blue
Year of manufacture	2008
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	200 Nm at 3.500 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	41.5 mpg
Consumption combined	33.2 mpg
CO2 emission	198 g/km
CO2 label	J





Internet history

Entry 1	
Date	2021-12-27
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-25
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	17
Total items failed	6

MOT #16	2024-01-26 16:49
MOT test number	391633429246
Result	✓ Passed
Next expiry date	2025-01-25

MOT #15	2024-01-24 13:29
MOT test number	267315728322
Result	✗ Failed
Fail	Brake performance unable to be tested (1.2.1 (g))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2023-01-16 08:12
MOT test number	575397782487
Result	✓ Passed

MOT #13	2021-10-29 07:38
MOT test number	869722057491
Result	✓ Passed

**MOT #12** 2021-10-28 11:49**MOT test number** 394375151459**Result** ✗ Failed

- Advice** Brake pad(s) wearing thin Fronts (1.1.13 (a) (ii))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #11 2020-07-07 09:10**MOT test number** 206000241108**Result** ✓ Passed

- Advice** Rust coming out of o/s/f tyre tread.
- Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on inner edge (no cords). (5.2.3 (e))

MOT #10 2020-07-06 08:23**MOT test number** 290512603178**Result** ✗ Failed

- Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Rust coming out of o/s/f tyre tread.
- Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on inner edge (no cords). (5.2.3 (e))

MOT #9 2019-06-22 11:26**MOT test number** 961567402572**Result** ✓ Passed

**MOT #8** 2018-06-20 12:45**MOT test number** 596185862622**Result** ✓ Passed**Advice** Central Rear Upper High level brake light inop**MOT #7** 2018-06-15 09:26**MOT test number** 396084453361**Result** ✗ Failed**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**Advice** Central Rear Upper High level brake light inop**MOT #6** 2017-06-28 10:08**MOT test number** 579331146924**Result** ✓ Passed**MOT #5** 2016-06-25 08:38**MOT test number** 838980866208**Result** ✓ Passed**Advice** Centre Rear high level brake not working**MOT #4** 2015-06-27 10:35**MOT test number** 427648675166**Result** ✓ Passed**Notice** Age cracking to all tyres, rears - 7 years old**Notice** Headlight aims on lower limits



MOT #3	2013-11-26 15:36
MOT test number	427900133414
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2012-12-04 11:39
MOT test number	475299532314
Result	✓ Passed

MOT #1	2011-12-02 11:55
MOT test number	716316131380
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
25 January 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 AK58MDZ
Plate since	2019-09-29
Current registration	 AK58MDZ
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-12-18
Last registration	2024-01-26
Complete history	See info



Registration #1	2008-12-18	13 mi
Registration #2	2011-12-02	18.729 mi
Registration #3	2012-12-04	22.117 mi
Registration #4	2013-11-26	25.657 mi
Registration #5	2015-06-27	31.245 mi
Registration #6	2016-06-25	33.814 mi
Registration #7	2017-06-28	36.799 mi
Registration #8	2018-06-15	39.510 mi
Registration #9	2018-06-20	39.510 mi
Registration #10	2019-06-20	39.510 mi
Registration #11	2019-06-20	39.510 mi
Registration #12	2019-06-20	39.510 mi
Registration #13	2019-06-20	39.510 mi
Registration #14	2019-06-20	39.510 mi
Registration #15	2019-06-20	39.510 mi
Registration #16	2019-06-20	39.510 mi
Registration #17	2019-06-20	39.510 mi
Registration #18	2019-06-20	39.510 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1590 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BVY 139152