



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK200 ELEGANCE
Colour	Blue
Year of manufacture	2005
Top speed	142 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	31.7 mpg
CO2 emission	206 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-03-19
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-24
MOT pass rate	94 %
MOT passed	16
Failed MOT tests	1
Total advice items	15
Total items failed	4

MOT #17	2023-07-25 12:30
MOT test number	267906061467
Result	✓ Passed
Next expiry date	2024-07-24
Advice	Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #16	2022-04-11 13:54
MOT test number	629708235035
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2021-04-01 07:56
MOT test number	523884981013
Result	✓ Passed

MOT #14	2020-03-21 09:59
MOT test number	630088490992
Result	✓ Passed
Advice	Nearside parking brake slightly low effort

**MOT #13** 2019-03-16 13:04**MOT test number** 347915341533**Result** ✓ Passed**MOT #12** 2018-03-24 11:36**MOT test number** 924738079689**Result** ✓ Passed**MOT #11** 2017-03-16 14:48**MOT test number** 501308071030**Result** ✓ Passed**MOT #10** 2017-03-16 14:07**MOT test number** 877733412073**Result** ✗ Failed**Fail** Exhaust system not adequately supported bracket (7.1.1)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Front Bonnet retaining device slightly deteriorated damaged (8.4.2)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**MOT #9** 2016-03-12 11:02**MOT test number** 981601795019**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Tyre worn close to the legal limit inner and outer edges (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit inner and outer edges (4.1.E.1)

**MOT #8** 2015-03-24 16:00**MOT test number** 779883285005**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-03-08 15:32**MOT test number** 166907964064**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #6** 2013-04-04 15:49**MOT test number** 547594993058**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-07-25 12:43**MOT test number** 295717602261**Result** ✓ Passed**MOT #4** 2011-07-28 12:41**MOT test number** 575259701245**Result** ✓ Passed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Notice** Engine Management warning lamp on



MOT #3	2010-06-30 16:55
MOT test number	674521780170
Result	✓ Passed
MOT #2	2009-06-30 10:48
MOT test number	634511789132
Result	✓ Passed
MOT #1	2008-07-16 13:15
MOT test number	230228498114
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 April 2024

✓

MOT

Expires:
24 July 2024

Tax status	Expired at 1 April 2024
Days left	29 days too late
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 ET05WSO
Plate since	2024-03-29
Current registration	 ET05WSO
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-07-29
Last registration	2023-07-25
Complete history	See info



Registration #1	2005-07-29	7 mi
Registration #2	2008-07-16	39.067 mi
Registration #3	2009-06-30	44.839 mi
Registration #4	2010-06-30	51.404 mi
Registration #5	2011-07-28	57.546 mi
Registration #6	2012-07-25	66.381 mi
Registration #7	2013-04-04	68.400 mi
Registration #8	2014-03-08	75.706 mi
Registration #9	2015-03-24	88.681 mi
Registration #10	2016-03-12	97.831 mi
Registration #11	2016-03-12	97.831 mi
Registration #12	2016-03-12	97.831 mi
Registration #13	2016-03-12	97.831 mi
Registration #14	2016-03-12	97.831 mi
Registration #15	2016-03-12	97.831 mi
Registration #16	2016-03-12	97.831 mi
Registration #17	2016-03-12	97.831 mi
Registration #18	2016-03-12	97.831 mi
Registration #19	2016-03-12	97.831 mi

More info >



Dimensions & weight

Width	1740 mm
Height	1413 mm
Length	4638 mm
Wheel base	2715 mm
Kerb weight	1615 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27194030536557