



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Black
Year of manufacture	2010
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 2


Date	2021-08-12
Pictures	14
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-12
Pictures	14
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-26
MOT pass rate	100 %
MOT passed	11
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #11 2023-09-27 10:11

MOT test number 704303040058

Result ✓ Passed

Next expiry date 2024-09-26

**Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced  
Corrosion on various places (6.1.1 (c) (i))

MOT #10 2022-09-08 09:53

MOT test number 633320421369

Result ✓ Passed

**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2021-08-26 13:16

MOT test number 859809143056

Result ✓ Passed

**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre tread wearing on inner edge (5.2.3 (e))

MOT #8 2020-09-01 08:49

MOT test number 666451296085

Result ✓ Passed

**MOT #7** 2019-08-14 16:25**MOT test number** 611761566874**Result** ✓ Passed**MOT #6** 2018-08-01 14:50**MOT test number** 439857461429**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #5** 2017-08-17 09:02**MOT test number** 731146205476**Result** ✓ Passed**Advice** Offside Front sun visor doesn't stay up**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Upper Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #4** 2016-08-19 09:16**MOT test number** 447905909629**Result** ✓ Passed**MOT #3** 2015-08-20 09:08**MOT test number** 704776582473**Result** ✓ Passed



MOT #2	2014-08-20 10:58
MOT test number	588212634234
Result	✓ Passed

MOT #1	2013-08-29 15:59
MOT test number	578891743264
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
26 September 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	26 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-10-20
Last registration	2023-09-27
Complete history	<a href="#">See info</a>



Registration #1	2010-10-20	26 mi
Registration #2	2013-08-29	36.775 mi
Registration #3	2014-08-20	41.866 mi
Registration #4	2015-08-20	47.345 mi
Registration #5	2016-08-19	54.859 mi
Registration #6	2017-08-17	63.583 mi
Registration #7	2018-08-01	69.490 mi
Registration #8	2019-08-01	75.397 mi
Registration #9	2020-08-01	81.304 mi
Registration #10	2021-08-01	87.211 mi
Registration #11	2022-08-01	93.118 mi
Registration #12	2023-08-01	99.025 mi
Registration #13	2024-08-01	104.932 mi
Registration #14	2025-08-01	110.839 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1200628