



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO SPORT TDCI
Colour	Blue
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	46.3 mpg
CO2 emission	161 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-31
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-05-06
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	27
Total items failed	4

MOT #19	2023-04-17 15:21
MOT test number	690182520117
Result	✓ Passed
Next expiry date	2024-05-06

MOT #18	2023-04-17 11:07
MOT test number	562149170568
Result	✗ Failed
MAJOR	Offside Rear Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
MAJOR	Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
MAJOR	Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #17	2022-05-03 11:53
MOT test number	397446966510
Result	✓ Passed
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #16** 2021-04-27 15:49**MOT test number** 851848095486**Result** ✓ Passed**MOT #15** 2021-04-20 09:51**MOT test number** 883572817616**Result** ✗ Failed**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #14** 2020-05-07 14:05**MOT test number** 764802465020**Result** ✓ Passed**MOT #13** 2019-10-10 08:52**MOT test number** 696623288556**Result** ✗ Failed**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**MAJOR** Exhaust emissions exceed manufacturer's specified limit Limit 1.45 (8.2.2.2 (a))**MAJOR** Rear Brake pipe excessively corroded Front to rear pipes (1.1.11 (c))**MOT #12** 2018-05-08 10:55**MOT test number** 753332952595**Result** ✓ Passed**Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #11** 2017-07-24 13:15**MOT test number** 936484114141**Result** ✓ Passed**Advice** Nearside front tyre worn on edges**MOT #10** 2016-06-03 10:12**MOT test number** 455528070154**Result** ✓ Passed**MOT #9** 2016-06-02 10:17**MOT test number** 856601379157**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear wheel bearing has excessive play (2.6.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2015-06-01 12:45**MOT test number** 287942955173**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #7** 2015-06-01 12:45**MOT test number** 206142455452**Result** ✗ Failed**Pass with rectification** Rear Direction indicators incorrect colour (1.4.A.2f)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #6** 2014-05-23 13:32**MOT test number** 529263444177**Result** ✓ Passed**MOT #5** 2014-05-23 13:32**MOT test number** 297473544179**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**MOT #4** 2013-05-23 10:15**MOT test number** 327783543107**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2012-05-21 15:15**MOT test number** 229212742137**Result** ✓ Passed**MOT #2** 2011-05-26 11:05**MOT test number** 168666441149**Result** ✓ Passed**Notice** Handbrake lever near to maximum allowed travel.**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front brake disc's worn.**MOT #1** 2010-05-27 16:14**MOT test number** 250117440161**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
6 May 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	6 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	KF07NHB
Plate since	2019-03-28
Current registration	KF07NHB
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-12
Last registration	2023-04-17
Complete history	See info



Registration #1	2007-03-12	16 mi
Registration #2	2010-05-27	39.435 mi
Registration #3	2011-05-26	47.680 mi
Registration #4	2012-05-21	59.090 mi
Registration #5	2013-05-23	65.289 mi
Registration #6	2014-05-23	71.309 mi
Registration #7	2015-06-01	79.086 mi
Registration #8	2016-06-02	85.399 mi
Registration #9	2016-06-03	85.400 mi
Registration #10	2017-07-24	91.872 mi
Registration #11	2018-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2020-05-29	95.377 mi
Registration #14	2021-05-29	95.377 mi
Registration #15	2022-05-29	95.377 mi
Registration #16	2023-05-29	95.377 mi
Registration #17	2024-05-29	95.377 mi
Registration #18	2025-05-29	95.377 mi
Registration #19	2026-05-29	95.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1958 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Kerb weight	1484 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7K34357