



report date: 2024-03-29

General information

Make	NISSAN
Model	CUBE 16V
Colour	White
Year of manufacture	2010
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	153 Nm at 4.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	151 g/km
CO2 label	G








Internet history

Entry 1

Date	2022-05-22
Pictures	16
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-07
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	45
Total items failed	20

MOT #15	2024-04-08 14:39
MOT test number	819639251099
Result	✓ Passed
Next expiry date	2025-04-07
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #14	2024-04-04 15:52
MOT test number	723166443860
Result	✗ Failed
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
Fail	Offside Parking brake inoperative on one side (1.4.1 (a))



## MOT #13

2023-04-05 14:05

MOT test number

723831597311

## Result

✓ Passed

**Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

## MOT #12

2023-04-05 14:05

MOT test number

509399144901

## Result

✗ Failed

**Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Pass with rectification** Windscreen washer not working (3.5 (a))

## MOT #11

2022-03-04 09:29

MOT test number

751021201030

## Result

✓ Passed

**Advice** Corrosion under vehicle/ suspension components

**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**Minor** Registration plate lamp insecure Both rear (4.7.1 (c) (i))

**MOT #10**

2022-02-24 12:50

**MOT test number**

137165330340

**Result****✗ Failed**

- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Front Macpherson strut pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Corrosion under vehicle/ suspension components
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Minor** Registration plate lamp insecure Both rear (4.7.1 (c) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Macpherson strut pin or bush excessively worn (5.3.4 (a) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**MOT #9** 2021-01-28 12:10**MOT test number** 551730106792**Result** ✓ Passed**MOT #8** 2020-02-21 17:25**MOT test number** 564460654862**Result** ✓ Passed**Advice** Oil sump corroded**Advice** Tyre worn close to legal limit/worn on edge both front 3mm 195/55/16 (5.2.3 (e))**Advice** Brake pipe corroded, covered in grease or other material both rear (1.1.11 (c))**MOT #7** 2020-02-14 14:55**MOT test number** 939776876790**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Brake pipe corroded, covered in grease or other material both rear (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Position lamp not working both front (4.2.1 (a) (ii))**Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps both rear (4.7.1 (b) (ii))**Advice** Oil sump corroded**Advice** Tyre worn close to legal limit/worn on edge both front 3mm 195/55/16 (5.2.3 (e))

**MOT #6** 2019-02-23 11:50**MOT test number** 403570491764**Result** ✓ Passed

- Advice** Exhaust system corroded
- Advice** Brake pipe corroded, covered in grease or other material both rear outer (1.1.11 (c))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Tyre worn close to legal limit/worn on edge both rear 3mm (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))

**MOT #5** 2018-02-17 10:18**MOT test number** 407631312285**Result** ✓ Passed

- Advice** Front wipers worn
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Exhaust system corroded
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2017-02-27 11:49**MOT test number** 326117680819**Result** ✓ Passed**MOT #3** 2016-02-13 09:26**MOT test number** 859744320653**Result** ✓ Passed



MOT #2	2015-02-17 09:52
MOT test number	547658445075
Result	✓ Passed

MOT #1	2013-12-16 10:34
MOT test number	468190653406
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)





Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
7 April 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	7 April 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>RE60NWS</b>
Plate since	2024-03-29
Current registration	<b>RE60NWS</b>
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-12-29
Last registration	2024-04-08
Complete history	<a href="#">See info</a>



Registration #1	2010-12-29	7 mi
Registration #2	2013-12-16	20.773 mi
Registration #3	2015-02-17	29.518 mi
Registration #4	2016-02-13	37.098 mi
Registration #5	2017-02-27	44.509 mi
Registration #6	2018-02-17	51.695 mi
Registration #7	2019-02-23	57.716 mi
Registration #8	2020-02-14	63.069 mi
Registration #9	2020-02-21	63.191 mi
Registration #10	2020-02-21	63.191 mi
Registration #11	2020-02-21	63.191 mi
Registration #12	2020-02-21	63.191 mi
Registration #13	2020-02-21	63.191 mi
Registration #14	2020-02-21	63.191 mi
Registration #15	2020-02-21	63.191 mi
Registration #16	2020-02-21	63.191 mi
Registration #17	2020-02-21	63.191 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	64%
Pedestrian	56%
Safety systems	84%
Overall rating	74%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1680 mm
Length	3980 mm
Wheel base	2530 mm
Kerb weight	1230 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	264214