





report date: 2024-03-28

General information

Make	MINI
Model	COOPER D ONE D
Colour	White
Year of manufacture	2013
Top speed	114 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP	
Max. torque	215 Nm at 1.750 rpm	
Engine capacity	1.598 сс	
Cylinders	4	
Fuel type	Diesel	
Consumption city	67.3 mpg	
Consumption extra urban	80.7 mpg	
Consumption combined	74.3 mpg	
CO2 emission	99 g/km	
CO2 label	А	



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-06-01

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT hist	orv
----------	-----

MOT expiry date	2024-06-19
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	16
Total items failed	3

MOT #11	2023-06-08 14:42
MOT test number	235803471771
Result	✓ Passed
Next expiry date	2024-06-19

MOT #10	2022-06-20 09:02
MOT test number	487602648575
Result	√ Passed

MOT #9	2021-11-09 15:50
MOT test number	230212866802
Result	✓ Passed

MOT #8	207	20-10-22 11:42

MOT test number 660819060505

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7 2020-10-19 09:04

MOT test number 264853533386

Result X Failed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #6 2019-11-13 10:00

MOT test number 568458010261

Result ✓ Passed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #5 2019-11-13 10:00

MOT test number 717446003125

Result × Failed

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

Pass with rectification Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2	2016-11-17 10:49
MOT test number	950027839371
Result	✓ Passed
MOT #1	2016-06-27 05:53
MOT test number	695446851187
Result	✓ Passed
Advice Nearside Rear Nail in tyre	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check

Tax expired: 18 April 2024





Tax status	Expired at 18 April 2024
Days left	11 days too late
MOT expiry date	19 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



NX63WYR
report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Ow		la : -	
()\//	ner	nis	

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report I	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



NX63WYR report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-24
Last registration	2023-06-08
Complete history	See info



Registration #1	2013-09-24	16 mi
Registration #2	2016-06-27	29.004 mi
Registration #3	2016-11-17	34.768 mi
Registration #4	2017-11-13	45.693 mi
Registration #5	2018-11-15	57.653 mi
Registration #6	2019-11-13	70.475 mi
Registration #7	2019-11-13	70.475 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.777 es
Registration #13		10.377 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/1

Number of axles 2

Engine number 70728575