





report date: 2024-03-28

General information

Make	MINI
Model	MINI (R57) ONE
Colour	Black
Year of manufacture	2012
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-07-27

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-05-16
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	3
Total items failed	3

MOT #12	2023-05-16 13:55
MOT test number	495247828845
Result	✓ Passed
Next expiry date	2024-05-16

MOT #11	2023-05-16 09:32
MOT test number	147529371236
Result	X Failed
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Rear Nail in tyre Punctured	

MOT #10	2022-05-17 12:02
MOT test number	203354987348
Result	✓ Passed

MOT #9	2021-03-08 14:52
MOT test number	254334639221
Result	✓ Passed

MOT #8	2020-02-28 10:31
MOT test number	295371241916
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7	2019-03-08 10:59
MOT test number	266629246755
Result	✓ Passed
MOT #6	2018-06-11 09:58
MOT test number	231444723204
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2018-06-11 09:35
MOT test number	441506256357
Result	× Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Windscreen washer not working (3.5 (a))	

MOT #4	2017-06-14 09:04
MOT test number	230232751764
Result	✓ Passed
MOT #3	2016-06-16 09:47
MOT test number	261130784592
Result	✓ Passed
MOT #2	2015-06-24 17:08
MOT test number	908195575137
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2015-05-05 10:52

MOT test number 338845625127

Result

X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	16 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

Plate changes	More info >
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	SK UK
Plate since	
Current registration	UK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-05
Last registration	2023-05-16
Complete history	See info



Registration #1	2012-09-05	24 mi
Registration #2	2015-05-05	16.706 mi
Registration #3	2015-06-24	16.746 mi
Registration #4	2016-06-16	23.200 mi
Registration #5	2017-06-14	30.675 mi
Registration #6	2018-06-11	40.127 mi
Registration #7	2018-06-11	40.127 mi
Registration #8		11.777 ea
Registration #9		11.777 es
Registration #10		77.777 46
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine numberA024J283