






report date: 2024-03-29

General information

Make	FORD
Model	FIESTA ZETEC
Colour	Bronze
Year of manufacture	2018
Top speed	105 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	108 Nm
Engine capacity	1.084 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	64.2 mpg
CO2 emission	101 g/km
CO2 label	В



CarCheck.co.uk page 1/11



NV67KOX

report date: 2024-03-29

Internet history

Entry 4

Date 2021-12-22

Pictures 0

Listing price <u>View report</u>

source: heycar.co.uk

Entry 3

Date 2021-08-21

Pictures 34

Listing price <u>View report</u>









source: heycar.co.uk

Entry 2


Date 2021-07-24

Pictures 33

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-07-23
Pictures	10

Listing price <u>View report</u>

CarCheck.co.uk page 2/11









source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-08
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #5	2024-01-03 10:33
MOT test number	953276300256
Result	✓ Passed
Next expiry date	2025-01-08

MOT #4	2023-01-09 12:47
MOT test number	333204567694
Result	✓ Passed

MOT #3	2021-12-23 08:17
MOT test number	343206980612
Result	✓ Passed

MOT #2		2021-02-13 14:15
MOT test	number	453358130592
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



NV67KOX

report date: 2024-03-29

MOT #1 2021-02-13 12:54 **MOT test number** 319953411042 Result × Failed **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Windscreen washer not working (3.5 (a)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	8 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



NV67KOX

report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when misterly		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ve?

	More info	>
Plate changes See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-02-21
Last registration	2024-01-03
Complete history	See info



Registration #1	2018-02-21	24 mi
Registration #2	2021-02-13	9.673 mi
Registration #3	2021-02-13	9.673 mi
Registration #4		71.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
\$0566	

View the complete FORD factory list for this vehicle <u>here</u>.

The FORD factory car options list is only available in the premium report.

More info >

Safety ratings

S0567 S0569

NCAP rating	****
Adult	87%
Children	84%
Pedestrian	64%
Safety systems	60%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1978 mm
Height	1495 mm
Length	3969 mm
Wheel base	2489 mm
Kerb weight	1113 kg
Max. allowed weight	1620 kg

Additional information

Fuel delivery	Multi-Point Injection	
Number of doors	3	
Number of seats	5	
Engine number Carcheck.co.uk	HR62931	page 11/11