



report date: 2024-03-29

General information

Make	VOLVO
Model	S80 D5 SE LUX
Colour	Gold
Year of manufacture	2006
Top speed	140 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history



Entry 2

Date	2022-01-27
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

Date	2021-11-25
Pictures	16
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-01
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	29
Total items failed	10

MOT #21 2024-01-02 09:25

MOT test number 315253037690

Result ✓ Passed

Next expiry date 2025-01-01

Advice Rear Exhaust silencer slightly loose (8.1.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened rear both. (1.1.14 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #20 2023-12-30 12:40

MOT test number 301448632159

Result ✗ Failed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Emissions unable to be completed (8.2.1.2 (d))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened rear both. (1.1.14 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Exhaust silencer slightly loose (8.1.1 (b) (i))

**MOT #19** 2021-12-24 15:56**MOT test number** 389179359136**Result** ✓ Passed**MOT #18** 2020-11-24 12:19**MOT test number** 148919630159**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing Both rear tyres have very slight perishing not to excess. (5.2.3 (d) (ii))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Rear Both rear trailing arms front bushes showing slight signs of deterioration, not to excess.**MOT #17** 2020-11-24 12:19**MOT test number** 464868551832**Result** ✗ Failed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Rear Both rear trailing arms front bushes showing slight signs of deterioration, not to excess.**Advice** Rear Tyre slightly damaged/cracking or perishing Both rear tyres have very slight perishing not to excess. (5.2.3 (d) (ii))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively Both front blades split. (3.4 (b) (ii))**MOT #16** 2019-11-13 11:55**MOT test number** 507701269366**Result** ✓ Passed**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bushes (5.3.4 (a) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bushes (5.3.4 (a) (i))**Advice** Rear Tyres starting to perish

**MOT #15** 2018-11-12 08:55**MOT test number** 822736808064**Result** ✓ Passed**MOT #14** 2017-11-16 16:13**MOT test number** 502853811416**Result** ✓ Passed**MOT #13** 2017-11-16 10:03**MOT test number** 796540839502**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #12** 2016-12-05 09:54**MOT test number** 720895459384**Result** ✓ Passed**MOT #11** 2015-12-04 09:34**MOT test number** 303433656823**Result** ✓ Passed**Advice** Covers & trays fitted**MOT #10** 2014-11-27 16:59**MOT test number** 747931234354**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Off and near side rear tyres tread show uneven wear and are extensively out of shape.**Notice** Under-trays fitted obscuring some underside components**Notice** Off and near side rear brake discs show wear/lipped edge.

**MOT #9** 2014-11-27 09:41**MOT test number** 345371834356**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Off and near side rear tyres tread show uneven wear and are extensively out of shape.**Notice** Under-trays fitted obscuring some underside components**Notice** Off and near side rear brake discs show wear/lipped edge.**MOT #8** 2013-12-07 10:04**MOT test number** 336841443312**Result** ✓ Passed**Notice** Offside and nearside rear tyres are extensively out of shape**MOT #7** 2012-12-12 15:47**MOT test number** 609447442385**Result** ✓ Passed**MOT #6** 2012-12-11 17:07**MOT test number** 348536042335**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2012-03-29 12:52**MOT test number** 657619082088**Result** ✓ Passed

**MOT #4** 2012-03-29 12:52**MOT test number** 717769482041**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #3** 2011-02-23 12:21**MOT test number** 847944551089**Result** ✓ Passed**MOT #2** 2009-09-24 16:21**MOT test number** 762907069284**Result** ✓ Passed**Notice** Both front and offside rear tyres near to wear indicators on the centre of tread.**MOT #1** 2009-09-24 16:21**MOT test number** 653057769202**Result** ✗ Failed**Notice** Both front and offside rear tyres near to wear indicators on the centre of tread.**Pass with rectification** Rear registration plate font not substantially similar to the prescribed font (6.3.4d)**Pass with rectification** Front registration plate font not substantially similar to the prescribed font (6.3.4d)



Tax & MOT check

X

Untaxed

Tax expired:
9 November 2022

✓

MOT

Expires:
1 January 2025

Tax status	Expired at 9 November 2022
Days left	536 days too late
MOT expiry date	1 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-09-14
Last registration	2024-01-02
Complete history	See info



Registration #1	2006-09-14	11 mi
Registration #2	2009-09-24	19.956 mi
Registration #3	2011-02-23	25.901 mi
Registration #4	2012-03-29	32.875 mi
Registration #5	2012-12-11	40.247 mi
Registration #6	2012-12-12	40.247 mi
Registration #7	2013-12-07	52.113 mi
Registration #8	2014-11-27	59.290 mi
Registration #9	2014-11-27	59.290 mi
Registration #10	2015-12-04	64.853 mi
Registration #11	2016-12-05	68.810 mi
Registration #12	2019-05-29	75.377 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2019-05-29	75.377 mi
Registration #15	2019-05-29	75.377 mi
Registration #16	2019-05-29	75.377 mi
Registration #17	2019-05-29	75.377 mi
Registration #18	2019-05-29	75.377 mi
Registration #19	2019-05-29	75.377 mi
Registration #20	2019-05-29	75.377 mi
Registration #21	2019-05-29	75.377 mi
Registration #22	2019-05-29	75.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1587 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number

418526