





report date: 2024-03-29

## General information

Make	PEUGEOT
Model	207 S
Colour	Blue
Year of manufacture	2010
Top speed	106 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	74 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/13



LA10FPF

report date: 2024-03-29

## Internet history


### Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-02-06
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	25
Total items failed	5

MOT #13		2024-02-02 15:56
MOT test	number	354523902003
Result		✓ Passed
Next expi	ry date	2025-02-06
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside washer jet weak	

CarCheck.co.uk page 3/13



MOT #12 2024-02-02 15:56

**MOT test number** 943753880258

Result X Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Exhaust system insecure (6.1.2 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside washer jet weak

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #11** 2023-02-07 14:16

MOT test number 183422513827

**Result** ✓ Passed

**Advice** Both rear tyres starting to crack/perish

**Advice** Exhaust mounting defective Rear silencer bracket (6.1.2 (a))

**Advice** Front washers weak

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 4/13



LA10FPF

report date: 2024-03-29

MOT #10	2023-01-30 09:45
MOT test number	861096086141
Result	<b>×</b> Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Both rear tyres starting to crack/perish	
Advice Exhaust mounting defective Rear silencer bracket (6.1.2 (a))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice Front washers weak	
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #9	2022-01-27 14:44
MOT test number	533652673284
Result	✓ Passed
MOT #8	2021-01-06 13:40
MOT test number	828354683731
Result	✓ Passed
MOT #7	2019-07-15 09:35
MOT test number	242002505567
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 5/13



MOT #6 2018-07-18 08:35

**MOT test number** 953715119250

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #5 2017-07-20 08:12

MOT test number 386682227932

**Result** ✓ Passed

**Advice** Nearside Rear tyre wall has slight damage

**Advice** Oil leak

MOT #4 2016-07-14 10:52

**MOT test number** 337585729520

**Result** ✓ Passed

MOT #3 2015-07-09 12:43

MOT test number 588060095175

**Result** ✓ Passed

MOT #2 2014-07-10 09:19

**MOT test number** 269921194410

**Result** 
✓ Passed

**Notice** Nearside front tyre has cut in side wall.

MOT #1 2013-07-11 09:40

**MOT test number** 266382093429

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	6 February 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



## Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



LA10FPF

report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner History	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
*********	
***************************************	
***********	
**********	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

**Contact info** 


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-07-30
Last registration	2024-02-02
Complete history	See info



Registration #1	2010-07-30	9 mi
Registration #2	2013-07-11	9.211 mi
Registration #3	2014-07-10	12.731 mi
Registration #4	2015-07-09	15.717 mi
Registration #5	2016-07-14	19.867 mi
Registration #6	2017-07-20	23.695 mi
Registration #7	2018-07-18	26.788 mi
Registration #8	2019-07-15	29.865 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11.177 ms

More info >

CarCheck.co.uk page 12/13



# Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1215 kg
Max. allowed weight	1617 kg

# Additional information

Fuel tank capacity	50	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	e 13/13

Number of axles 2

Engine number FSW86309213