



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 SE LUX
Colour	Black
Year of manufacture	2009
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





MOT history

MOT expiry date	2025-04-07
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	26
Total items failed	8

MOT #17	2024-04-08 12:58
MOT test number	127474048780
Result	✓ Passed
Next expiry date	2025-04-07

MOT #16	2024-04-03 15:54
MOT test number	842136303534
Result	✗ Failed
MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))	
DANGEROUS Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #15	2023-04-04 13:44
MOT test number	305767486691
Result	✓ Passed

MOT #14	2022-04-04 11:30
MOT test number	444368491658
Result	✓ Passed

**MOT #13** 2021-03-24 13:14**MOT test number** 116055598356**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #12** 2020-02-05 11:31**MOT test number** 964498403414**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2020-02-05 11:31**MOT test number** 756946012686**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #10** 2019-03-18 10:40**MOT test number** 336358849425**Result** ✓ Passed**Advice** Offside Front Macpherson strut mounting damaged but not seriously weakened (5.3.3 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9** 2018-03-14 11:38**MOT test number** 721565000684**Result** ✓ Passed**Advice** Both rear tyres misshapen**MOT #8** 2016-02-27 10:10**MOT test number** 566880756359**Result** ✓ Passed**MOT #7** 2016-02-27 10:10**MOT test number** 139045033493**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2015-01-27 15:54**MOT test number** 199317625492**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-01-26 12:05**MOT test number** 667556125027**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-02-19 10:24**MOT test number** 217540254020**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2014-02-13 12:46**MOT test number** 305224144032**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Nearside headlamp beam light output slightly reduced**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Headlamp aim too far to the right (1.8)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-02-13 16:45**MOT test number** 905854743052**Result** ✓ Passed



MOT #1	2012-02-23 11:46
MOT test number	338614952010
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
7 April 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	7 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	PX09XGN
Plate since	2019-09-29
Current registration	PX09XGN
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-05-19
Last registration	2024-04-08
Complete history	See info



Registration #1	2009-05-19	6 mi
Registration #2	2012-02-23	19.463 mi
Registration #3	2013-02-13	34.423 mi
Registration #4	2014-02-13	45.932 mi
Registration #5	2014-02-19	45.971 mi
Registration #6	2015-01-26	59.423 mi
Registration #7	2015-01-27	59.458 mi
Registration #8	2016-02-27	73.761 mi
Registration #9	2016-02-27	73.761 mi
Registration #10	2016-05-20	75.377 mi
Registration #11	2016-05-20	75.377 mi
Registration #12	2016-05-20	75.377 mi
Registration #13	2016-05-20	75.377 mi
Registration #14	2016-05-20	75.377 mi
Registration #15	2016-05-20	75.377 mi
Registration #16	2016-05-20	75.377 mi
Registration #17	2016-05-20	75.377 mi
Registration #18	2016-05-20	75.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1344 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	175195