



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE
Colour	Blue
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-10-25
Pictures	21
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-21
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	14
Total items failed	6

MOT #12	2023-06-22 09:20
MOT test number	479804509750
Result	✓ Passed
Next expiry date	2024-06-21

MOT #11	2022-11-08 14:30
MOT test number	878209634599
Result	✓ Passed

MOT #10	2022-11-07 10:28
MOT test number	476301863972
Result	✗ Failed

**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9	2021-11-19 17:11
MOT test number	304665969185
Result	✓ Passed

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8** 2021-01-11 15:31**MOT test number** 863448551275**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7** 2019-12-11 17:32**MOT test number** 597499996443**Result** ✓ Passed

- Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** Offside Rear light lens damaged.

**MOT #6** 2019-12-03 16:02**MOT test number** 144011123667**Result** ✗ Failed

- Advice** Offside Rear light lens damaged.
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Pass with rectification** Offside Headlamp aim too far to the right (4.1.2 (a))

**MOT #5** 2018-09-28 12:54**MOT test number** 586126151072**Result** ✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing side wall to tread join. (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing side wall to tread join. (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge. (5.2.3 (e))



<b>MOT #4</b>	2017-08-05 09:53
<b>MOT test number</b>	872389894868
<b>Result</b>	✓ Passed
<div><b>Advice</b> Offside Front tyre perishing on tread</div>	
<b>MOT #3</b>	2016-07-26 12:59
<b>MOT test number</b>	671686621562
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2016-07-25 11:03
<b>MOT test number</b>	663578789582
<b>Result</b>	✗ Failed
<div><b>Fail</b> Nearside Front coil spring broken (2.4.C.1a)</div> <div><b>Fail</b> Offside Front coil spring broken (2.4.C.1a)</div>	
<b>MOT #1</b>	2015-06-15 07:59
<b>MOT test number</b>	356496265181
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
21 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	21 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-04-02
Last registration	2023-06-22
Complete history	<a href="#">See info</a>



Registration #1	2012-04-02	20 mi
Registration #2	2015-06-15	57.270 mi
Registration #3	2016-07-25	59.831 mi
Registration #4	2016-07-26	59.831 mi
Registration #5	2017-08-05	62.802 mi
Registration #6	2018-09-28	64.824 mi
Registration #7	2019-12-03	71.627 mi
Registration #8	2020-06-22	75.270 mi
Registration #9	2021-06-22	75.270 mi
Registration #10	2022-06-22	75.270 mi
Registration #11	2023-06-22	75.270 mi
Registration #12	2024-06-22	75.270 mi
Registration #13	2025-06-22	75.270 mi
Registration #14	2026-06-22	75.270 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2041867