



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	Silver
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-07
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-29
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	16
Total items failed	13

MOT #17 2024-04-16 14:21

MOT test number 269216236683

Result ✗ Failed

Minor Front Position lamp incorrect colour (4.2.3 (a) (i))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #16 2023-04-15 14:37

MOT test number 747773290705

Result ✓ Passed

MOT #15 2022-04-13 12:30

MOT test number 654884103287

Result ✓ Passed

MOT #14 2021-04-30 13:22

MOT test number 333537707729

Result ✓ Passed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #13** 2020-03-26 16:39**MOT test number** 312023934869**Result** ✓ Passed**MOT #12** 2019-01-23 09:35**MOT test number** 957952245479**Result** ✓ Passed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Nail in tyre

MOT #11 2019-01-23 09:35**MOT test number** 597527959781**Result** ✗ Failed

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))

Advice Nearside Rear Nail in tyre

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Central Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

MOT #10 2018-01-02 09:04**MOT test number** 668028792101**Result** ✓ Passed**MOT #9** 2017-01-11 16:17**MOT test number** 268680686701**Result** ✓ Passed

**MOT #8** 2017-01-09 09:24**MOT test number** 392312671237**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Rear Brake pad(s) wearing thin right on limit (3.5.1g)**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit and worn on inner edge (4.1.E.1)**MOT #7** 2016-01-07 10:43**MOT test number** 805903195123**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2016-01-07 10:43**MOT test number** 325082482200**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp excessively damaged so that the light output is severely reduced (1.7.5a)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #5** 2014-12-24 08:51**MOT test number** 416418154387**Result** ✓ Passed

**MOT #4** 2014-12-18 09:19**MOT test number** 725362954391**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Offside rear tyre perished**MOT #3** 2014-01-07 09:16**MOT test number** 165127904489**Result** ✓ Passed**MOT #2** 2014-01-07 09:16**MOT test number** 149097804099**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #1** 2013-01-07 10:29**MOT test number** 518347703053**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Chips in screen**Notice** Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
29 April 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	29 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LC59NWH
Plate since	2019-09-28
Current registration	LC59NWH
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-12-20
Last registration	2024-04-16
Complete history	See info



Registration #1	2009-12-20	28 mi
Registration #2	2013-01-07	14.016 mi
Registration #3	2014-01-07	25.651 mi
Registration #4	2014-12-18	36.612 mi
Registration #5	2014-12-24	36.790 mi
Registration #6	2016-01-07	50.553 mi
Registration #7	2016-01-07	50.553 mi
Registration #8	2017-01-09	59.645 mi
Registration #9	2017-01-11	59.645 mi
Registration #10	2019-05-20	59.557 mi
Registration #11	2019-05-20	59.557 mi
Registration #12	2019-05-20	59.557 mi
Registration #13	2019-05-20	59.557 mi
Registration #14	2019-05-20	59.557 mi
Registration #15	2019-05-20	59.557 mi
Registration #16	2019-05-20	59.557 mi
Registration #17	2019-05-20	59.557 mi
Registration #18	2019-05-20	59.557 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	704037