





General information

DSTYLE
nds
lanual
r

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	А







Internet history

Entry 3	
Date	2022-01-16
Pictures	20
Listing price	View report



source: cargurus.co.uk

Entry 2	
Date	2022-01-13
Pictures	10
Listing price	View report



source: autoonline.co.uk

Entry 1	
Date	2022-01-01
Pictures	0
Listing price	View report

source: heycar.co.uk



MOT history

MOT expiry date	2025-01-19
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	11
Total items failed	2

MOT #11	2024-01-05 09:51
MOT test number	528756508624
Result	🗸 Passed
Next expiry date	2025-01-19
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #10	2023-01-09 15:22
MOT test number	406541566584
Result	✓ Passed

МОТ #9	2023-01-09 10:03
MOT test number	107748285437
Result	🗙 Failed
MAJOR Headlamp light source and lamp not compatible (4.1.4 (c))	
DANGEROUS Nearside Front Tyre has a bulge, caused by separation or partial fail(5.2.3 (d) (ii))	ilure of its structure

MOT #8	2022-01-20 16:18
MOT test number	844435057644
Result	✓ Passed





MOT #7	2021-07-19 10:51
MOT test number	191771853635
Result	✓ Passed
MOT #6	2020-08-03 11:56

	2020 00 00 11.00
MOT test number	566250296601
Result	✓ Passed
Advice Duply discussors without an approach but not equipy by weakened all	broke diago front C. room (1, 1, 1, 4

Advice Brake disc worn, pitted or scored, but not seriously weakened all brake discs front & rear (1.1.14 (a) (ii))

MOT #5	2019-08-09 12:53
MOT test number	911542424260
Result	✓ Passed
Advice Rear Brake disc worn, pitted or scored, but not seriously weaker (ii))	ned pitted inside face (1.1.14 (a)

MOT #4		2019-08-09 09:28
MOT test I	number	298280079250
Result		🗙 Failed
MAJOR Advice	Rear Registration plate lamp inoperative in the case of a single lamp or all Rear Brake disc worn, pitted or scored, but not seriously weakened pitted	
(ii)) MAJOR Advice	Central Front Exhaust system insecure (6.1.2 (a)) Front Tyre worn close to legal limit/worn on edge both side and worn inside	e face 2mm (5.2.3 (e))

MOT #3	2019-02-12 15:1	.3
MOT test	number 64632843186	51
Result	V Passe	ed .
Advice	Central Front Exhaust mounting defective Exhaust mounting cracked (6.1.2 (a))	
Advice Offside Front Tyre worn close to legal limit/worn on edge Worn on inner edge. Off side front. (5.2.3 (e))		3





MOT #2	2018-02-14 15:31	
MOT test number	973090372772	
Result	✓ Passed	
MOT #1	2018-02-14 15:31	
MOT test number	505540164550	
Result	× Failed	
Pass with rectification	Pass with rectification Front brake disc in such a condition that it is seriously weakened (3.5.1i)	
Pass with rectification	tion Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 19 January 2025
Tax status	Valid until 1 January
Days left	248
MOT expiry date	19 January 2025
Full MOT history	See MOT history
Tax calculation	
Vehicle class	49

	•
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lamp
Туре		
Damage 2		AMPL
Date		· · ·
Category	1000000	AMPL
Туре		

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	

More info \rightarrow





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-01-14
Last registration	2024-01-05
Complete history	See info



Registration #1	2015-01-14	12 mi
Registration #2	2018-02-14	26.911 mi
Registration #3	2018-02-14	26.911 mi
Registration #4	2019-02-12	31.578 mi
Registration #5	2019-08-09	35.787 mi
Registration #6	2019-08-09	35.790 mi
Registration #7	2020-08-03	38.776 mi
Registration #8	2021-07-19	43.098 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 mi

More info >





Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg
Additional information	
Additional information Fuel tank capacity	48
	48 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 3