





report date: 2024-03-28

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Silver
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	77 kW / 105 HP / 104 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-01

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-12-12
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	13
Total items failed	5

MOT #12	2023-12-13 15:49
MOT test number	324957773375
Result	✓ Passed
Next expiry date	2024-12-12

MOT #11	2023-12-13 10:09
MOT test number	854612370299
Result	X Failed
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #10		2022-12-05 11:25
MOT test	number	518249015074
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Both edges (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Both edges (5.2.3 (e))	
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #9	2021-11-24 14:42
MOT test number	318519394432
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #8

MOT test number

Result

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7 2020-12-02 10:45 **MOT** test number 595297988415 Result × Failed **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Front Brake pad(s) less than 1.5 mm thick Close to metal on edge of brake pads (1.1.13 (a) (ii))

MOT #6

MOT test number

173966392604

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5

MOT test number

Result

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Fail Offside Front Tyre has ply or cords exposed outer sidewall (5.2.3 (d) (ii))

MOT #3

MOT test number

Result

Advice

Offside Front Tyre worn close to the legal limit low on inside edge (4.1.E.1)

Advice

Offside Front Seat belt stitching slightly frayed (5.2.2b)

MOT #2

MOT test number

447695020755

Result

✓ Passed

MOT #1 2015-12-04 15:08

MOT test number 190635742683

Result ✓ Passed

CarCheck.co.uk page 5/12





Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Venicle class	40
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this FORD? How many owners defect it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-01-19
Last registration	2023-12-13
Complete history	See info



Registration #1	2013-01-19	20 mi
Registration #2	2015-12-04	17.239 mi
Registration #3	2016-11-16	23.178 mi
Registration #4	2017-11-24	27.351 mi
Registration #5	2018-11-29	32.821 mi
Registration #6	2018-11-29	32.822 mi
Registration #7	2019-12-02	39.130 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.117 es
Registration #13		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1208 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

CT29076