





General information

Make	KIA
Model	RIO 2
Colour	Blue
Year of manufacture	2013
Top speed	107 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	121 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С





MOT history

MOT expiry date	2021-06-29
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	21
Total items failed	2

MOT #7		2020-06-18 15:26
MOT test	number	790592171346
Result		✓ Passed
Next expiry date 2021-06-29		
Minor Offside Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))		
Minor	Minor Nearside Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))	

MOT #6	2020-06-18 15:26
MOT test number	802287788862
Result	× Failed
Minor Offside Front Sus	pension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Minor Nearside Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))	

MOT #5		2019-06-27 08:30
MOT test	t number	707244692247
Result		✓ Passed
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorate	ed (5.3.4 (b) (i))





MOT #4		2018-06-15 16:15
MOT test	number	687077344138
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm 195/55/16 (5.2.3 (e	2))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Nail in tyre on shoulder of tread/sidewall	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm 195/55/16 (5.2.3	(e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3		2018-06-14 10:38	
MOT test	number	878944228064	
Result		🗙 Failed	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm 195/55/16 (5.2.3 (e))		
Advice	Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm 195/55/16 (5.2.3 (e))		
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))		
FailNearside Front Tyre has a bulge, caused by separation or partial failure of its structure out of shape(5.2.3 (d) (i))			
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 ((a) (ii))	
Advice	Offside Rear Nail in tyre on shoulder of tread/sidewall		





MOT #2		2017-06-30 16:41
MOT test	number	126135876528
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin approx. 30% remaining (3.5.1g)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened lipped s	slightly (3.5.1i)

MOT #1	2016-07-28 08:19
MOT test number	345389062640
Result	✓ Passed





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2013-07-31
Last registration	2020-06-18
Complete history	See info



Registration #1	2013-07-31	15 mi
Registration #2	2016-07-28	21.565 mi
Registration #3	2017-06-30	36.597 mi
Registration #4	2018-06-14	48.957 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.317 esi





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1720 mm
Height	1455 mm
Length	4045 mm
Wheel base	2570 mm
Kerb weight	1211 kg
Max. allowed weight	1560 kg
Additional information	
Fuel tank capacity	43
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/10

|--|

Engine number

G4LACP057661