



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I20 ACTIVE
Colour	Blue
Year of manufacture	2012
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-20
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #12	2024-03-28 10:28
MOT test number	840587902375
Result	✓ Passed
Next expiry date	2025-04-20
Advice	Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #11	2023-03-31 13:34
MOT test number	141369644893
Result	✓ Passed
Advice	Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #10**

2023-03-31 09:50

MOT test number

747493142027

Result**✗ Failed****Fail**

Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail

Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9

2022-03-23 10:53

MOT test number

310970149770

Result**✓ Passed****Advice**

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8

2021-04-21 16:28

MOT test number

618251447839

Result**✓ Passed****Advice**

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #7** 2021-04-21 09:00**MOT test number** 314683932982**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid Both sides (3.5 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #6** 2019-11-29 11:31**MOT test number** 498495416923**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2018-11-30 15:46**MOT test number** 174904970117**Result** ✓ Passed**MOT #4** 2017-12-01 09:30**MOT test number** 103208577290**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2016-12-05 12:44**MOT test number** 898734877166**Result** ✓ Passed



MOT #2	2016-10-14 09:16
MOT test number	869980964711
Result	✓ Passed

MOT #1	2015-10-09 08:44
MOT test number	194482749530
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
20 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	20 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-10-17
Last registration	2024-03-28
Complete history	See info



Registration #1	2012-10-17	9 mi
Registration #2	2015-10-09	27.299 mi
Registration #3	2016-10-14	38.800 mi
Registration #4	2016-12-05	39.111 mi
Registration #5	2017-12-01	43.227 mi
Registration #6	2018-11-30	48.335 mi
Registration #7	2019-11-29	52.787 mi
Registration #8	2020-03-28	55.277 mi
Registration #9	2020-03-28	55.277 mi
Registration #10	2020-03-28	55.277 mi
Registration #11	2020-03-28	55.277 mi
Registration #12	2020-03-28	55.277 mi
Registration #13	2020-03-28	55.277 mi
Registration #14	2020-03-28	55.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1083 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4LACM870481