



report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 35 L2H1 120 MWB PV
Colour	White
Year of manufacture	2009
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2023-03-15
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	33
Total items failed	25

MOT #17 2022-03-16 13:59

MOT test number 395247351845

Result ✓ Passed

Next expiry date 2023-03-15

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Rear Direction indicator lens defective which has no effect on emitted light both sides (4.4.1 (b) (i))
- Advice** Rear Exhaust box slight corroded

MOT #16 2020-09-02 13:02

MOT test number 520491664979

Result ✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Front Leaf spring has slight wear in a shackle pin and/or bush front bush (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #15**

2019-08-16 12:55

MOT test number

547906983146

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Centre brake light not working**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #14**

2019-08-16 08:53

MOT test number

640907504638

Result

✗ Failed

Fail Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13**

2018-08-10 09:22

MOT test number

220020297956

Result

✓ Passed

Advice Water in offside headlight**Advice** Wipers**Advice** Front Coil spring corroded (5.3.1 (b) (i))



MOT #12 2018-08-06 11:19

MOT test number 941188547485

Result ✗ Failed

Advice Water in offside headlight

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Wipers

Advice Front Coil spring corroded (5.3.1 (b) (i))

MOT #11 2017-08-22 08:34

MOT test number 735994129414

Result ✓ Passed

Advice Unable to visually inspect rear brake pads

Advice Steering system slightly rough (2.2.D.1)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10**

2017-08-17 11:28

MOT test number

817298574627

Result**✗ Failed**

- Fail** Emissions not tested (7.3.A.1)
- Fail** Offside Rear fog lamp not working (1.3.2b)
- Fail** Registration plate lamp not working (1.1.C.1d)

Advice Unable to visually inspect rear brake pads**Advice** Oil leak**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Steering system slightly rough (2.2.D.1)**Advice** Cut in outer wall o/s/r tyre**MOT #9**

2016-08-03 12:17

MOT test number

960210970404

Result**✓ Passed****Advice** Oil leak**Advice** Front bumper split**Advice** Rear Tyre worn close to the legal limit Both sides (4.1.E.1)**MOT #8**

2015-05-29 15:07

MOT test number

128919245133

Result**✓ Passed**

**MOT #7** 2015-05-26 10:19**MOT test number** 305126745137**Result** ✗ Failed

- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Nearside Side repeater not working (1.4.A.2c)
- Fail** Nearside Rear Leaf spring has excessive wear in a shackle pin and/or bush (2.4.B.2)
- Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Direction indicator not working (1.4.A.2c)
- Fail** Offside Rear fog lamp not working (1.3.2b)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Offside Side repeater not working (1.4.A.2c)
- Fail** Offside Rear Leaf spring has excessive wear in a shackle pin and/or bush (2.4.B.2)
- Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)
- Fail** Offside Rear Direction indicator not working (1.4.A.2c)

MOT #6 2014-05-23 13:31**MOT test number** 679373544105**Result** ✓ Passed**MOT #5** 2014-05-23 12:39**MOT test number** 367003444155**Result** ✗ Failed

- Fail** Exhaust system not adequately supported (7.1.1)

**MOT #4** 2013-06-06 11:12**MOT test number** 746227253129**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2013-06-06 09:51**MOT test number** 129697253110**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2012-05-23 14:06**MOT test number** 415884342102**Result** ✓ Passed**MOT #1** 2012-05-23 14:06**MOT test number** 626954942197**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✕
Untaxed

Tax expired:
1 April 2023

✕
MOT

Expired:
15 March 2023

Tax status	Expired at 1 April 2023
Days left	393 days too late
MOT expiry date	15 March 2023
Full MOT history	See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-05-29
Last registration	2022-03-16
Complete history	See info



Registration #1	2009-05-29	12 mi
Registration #2	2012-05-23	26.906 mi
Registration #3	2013-06-06	35.591 mi
Registration #4	2013-06-06	35.591 mi
Registration #5	2014-05-23	49.230 mi
Registration #6	2014-05-23	49.230 mi
Registration #7	2015-05-26	54.645 mi
Registration #8	2015-05-29	54.645 mi
Registration #9	2016-08-03	64.158 mi
Registration #10	2016-08-03	64.158 mi
Registration #11	2016-08-03	64.158 mi
Registration #12	2016-08-03	64.158 mi
Registration #13	2016-08-03	64.158 mi
Registration #14	2016-08-03	64.158 mi
Registration #15	2016-08-03	64.158 mi
Registration #16	2016-08-03	64.158 mi
Registration #17	2016-08-03	64.158 mi

More info >



Dimensions & weight

Width	2508 mm
Height	2254 mm
Length	5413 mm
Kerb weight	1900 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJ20323463