





report date: 2024-03-29

### General information

| Make                | SUZUKI         |
|---------------------|----------------|
| Model               | SWIFT SZ-L     |
| Colour              | Red            |
| Year of manufacture | 2015           |
| Top speed           | 103 mph        |
| 0 - 60 mph          | 12.3 seconds   |
| Gearbox             | 5 speed Manual |

## Engine & fuel consumption

| Power                   | 94 BHP              |
|-------------------------|---------------------|
| Max. torque             | 118 Nm at 4.800 rpm |
| Engine capacity         | 1.242 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 46.3 mpg            |
| Consumption extra urban | 64.2 mpg            |
| Consumption combined    | 56.5 mpg            |
| CO2 emission            | 116 g/km            |
| CO2 label               | С                   |



CarCheck.co.uk page 1/11



YP15OTL report date: 2024-03-29

## Internet history

### Entry 2

Date 2021-07-03

Pictures 20

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1


| Date     | 2021-06-04 |
|----------|------------|
| Pictures | 19         |

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



report date: 2024-03-29

# MOT history

| MOT expiry date    | 2024-05-20 |
|--------------------|------------|
| MOT pass rate      | 86 %       |
| MOT passed         | 6          |
| Failed MOT tests   | 1          |
| Total advice items | 10         |
| Total items failed | 1          |

| MOT #7    |  | 2023-05-18 09:27 |
|-----------|--|------------------|
| MOT test  | number   | 514433443575     |
| Result    |  | ✓ Passed         |
| Next expi | ry date  | 2024-05-20       |
| Advice    | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice    | Rear Coil spring corroded (5.3.1 (b) (i))                              |                  |
| Advice    | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |
| Advice    | Tyre slightly damaged/cracking or perishing all 4 (5.2.3 (d) (ii))     |                  |
| Advice    | Nearside Front Coil spring corroded (5.3.1 (b) (i))                    |                  |

| MOT #6     |   | 2023-05-18 09:27 |
|------------|---|------------------|
| MOT test i | number  | 468893898584     |
| Result     |   | <b>×</b> Failed  |
| Pass wit   | h rectification Windscreen washer provides insufficient washer liquid (3.5 (a)) | )                |
| Advice     | Rear Coil spring corroded (5.3.1 (b) (i))                                       |                  |
| Advice     | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))           |                  |
| Advice     | Nearside Front Coil spring corroded (5.3.1 (b) (i))                             |                  |
| Advice     | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))          |                  |
| Advice     | Tyre slightly damaged/cracking or perishing all 4 (5.2.3 (d) (ii))              |                  |

CarCheck.co.uk page 3/11



Result

YP15OTL report date: 2024-03-29

✓ Passed

| MOT #5          | 2022-05-09 16:29 |
|-----------------|------------------|
| MOT test number | 493948886344     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #4          | 2021-05-20 14:08 |
| MOT test number | 798265026560     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #3          | 2020-05-11 12:21 |
| MOT test number | 203601468147     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #2          | 2019-04-25 12:24 |
| MOT test number | 620760383227     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #1          | 2018-05-03 12:52 |
| MOT test number | 882364529779     |

CarCheck.co.uk page 4/11



report date: 2024-03-29

# Tax & MOT check



| Tax status       | Valid until 1 July |
|------------------|--------------------|
| Days left        | 63                 |
| MOT expiry date  | 20 May 2024        |
| Full MOT history | See MOT history    |

### Tax calculation

| Vehicle class                           | 48             |
|---|----------------|
| Band                                    | С              |
| Single payment (12 months)              | £ 35,00,-      |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,-      |

CarCheck.co.uk page 5/11



report date: 2024-03-29

### Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Туре     |  |



#### Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



YP15OTL

report date: 2024-03-29

| Owner  | hictor,  |
|--------|----------|
| UWNEI  | nisioiv  |
| OWINCE | THISCOLY |

| For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full is |             |
|---|-------------|
| ***************************************   |             |
| ***************************************   |             |
| 200000000   |             |
|   |             |
|   |             |
|   |             |
|   |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this SUZUKI had different number plates.   |             |
| Number of plates  |             |
| Current registration  | NK SIX      |
| Plate since   |             |
| Current registration  | UK UK       |
| Plate since   |             |
|   | More info > |
|   |             |

CarCheck.co.uk page 8/11



report date: 2024-03-29

### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 10         |
| First mileage registration | 2015-05-21 |
| Last registration          | 2023-05-18 |
| Complete history           | See info   |



| Registration #1                 | 2015-05-21 | 21 mi                               |
|---------------------------------|------------|-------------------------------------|
| Registration #2                 | 2018-05-03 | 8.965 mi                            |
| Registration #3                 | 2019-04-25 | 12.581 mi                           |
| Registration #4                 | 2020-05-11 | 15.220 mi                           |
| Registration #5                 | 2021-05-20 | 17.264 mi                           |
|                                 |            |                                     |
| Registration #6                 |            | 11.777 es                           |
|                                 |            | 11.777 ea<br>11.777 ea              |
| Registration #6                 |            | 11.77 m                             |
| Registration #6 Registration #7 |            | 11.777 es<br>11.777 es<br>11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 94%             |
| Children       | 82%             |
| Pedestrian     | 62%             |
| Safety systems | 71%             |
| Overall rating | 83%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1695 mm |
|---------------------|---------|
| Height              | 1510 mm |
| Length              | 3850 mm |
| Wheel base          | 2430 mm |
| Kerb weight         | 1049 kg |
| Max. allowed weight | 1480 kg |

# Additional information

| Fuel tank capacity | 42 I                  |
|--------------------|-----------------------|
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 3                     |
| Number of seats    | 4                     |
| Number of axles    | 2                     |
| Engine number      | K12B-1870596          |

CarCheck.co.uk page 11/11