





General information

| Make | NISSAN |
|---------------------|-------------------|
| Model | LEAF |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 89 mph |
| 0 - 60 mph | 8.6 seconds |
| Gearbox | 1 speed automatic |

Engine & fuel consumption

| Power | 148 BHP |
|-------------|-------------|
| Max. torque | 320 Nm |
| Fuel type | Electricity |







Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2021-07-29 |
| Pictures | 23 |
| Listing price | View report |



source: autotrader.co.uk

Entry 1

Date

Pictures

Listing price

23 <u>View report</u>

2021-07-29



source: cargurus.co.uk









MOT history

| MOT expiry date | 2025-02-22 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 5 |
| Total items failed | 0 |

| MOT #6 | 2024-02-16 09:20 |
|------------------|------------------|
| MOT test number | 724534702811 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-22 |

| MOT #5 | 2023-02-23 10:52 |
|---|------------------|
| MOT test number | 529052128219 |
| Result | 🗸 Passed |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |

| MOT #4 | | 2022-03-10 10:35 |
|---|--|------------------|
| MOT test | number | 247319824682 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |

| MOT #3 | 2021-03-25 17:00 |
|-----------------|------------------|
| MOT test number | 659795695937 |
| Result | ✓ Passed |





| MOT #2 | 2021-03-19 17:01 |
|---|------------------|
| MOT test number | 135433931888 |
| Result | Passed |
| | |
| MOT #1 | 2021-03-18 17:23 |
| MOT test number | 455380705506 |
| Result | 🗙 Failed |
| AdviceOffside Front Tyre worn close to legal limit/worn on edge 2.4mm (5.2.3 (e))DANGEROUSNearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|--|-------|
| Date | F | |
| Category | | ARME |
| Туре | | |
| Damage 2 | | AMPLE |
| | E E | |
| Date | | \$ |
| Category | AMP | |
| Туре | No. Contraction of the second se | |

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|---|-------------|
| ************ | |
| ******** | |
| ******* | |
| ************ | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow



NU18CUO report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2018-03-30 |
| Last registration | 2024-02-16 |
| Complete history | See info |



| Registration #1 | 2018-03-30 | 13 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-03-18 | 31.348 mi |
| Registration #3 | 2021-03-19 | 31.362 mi |
| Registration #4 | 2021-03-25 | 31.533 mi |
| Registration #5 | | 11.117 esi |
| Registration #6 | | 11.177 esi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 esi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| \$0501 | |
| 50566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 93% |
| Children | 86% |
| Pedestrian | 71% |
| Safety systems | 71% |
| Overall rating | 82% |
| Video | see crash video |



| Dimensions & weight | |
|---------------------------------|--------------------|
| Width | 2030 mm |
| Height | 1540 mm |
| Length | 4490 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1176 kg |
| Max. allowed weight | 1995 kg |
| Additional information | |
| Fuel delivery | Not Applicable |
| Number of doors | 5 |
| Number of seats | 5 |
| Engine number Carcheck.co.uk | 132280Z page 10/10 |