



**HG58DPF**

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 260 SPORT LR P/V
Colour	White
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	350 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



## MOT history

MOT expiry date	2024-05-31
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	29
Total items failed	9

## MOT #18 2023-06-01 10:44

MOT test number 930274802469

Result ✓ Passed

Next expiry date 2024-05-31

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

## MOT #17 2022-03-23 16:06

MOT test number 307712403463

Result ✓ Passed

**Advice** Offside Rear Brake cable damaged but not to excess (1.1.15 (a))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Minor** Nearside Front Outer Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Nearside Front Non obligatory mirror damaged

**Minor** Offside Rear Stop lamp(s) lens defective which has no effect on emitted light (4.3.1 (b) (i))

**Advice** Nearside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #16** 2021-03-17 09:21**MOT test number** 244081191457**Result** ✓ Passed**MOT #15** 2019-09-19 17:44**MOT test number** 908066410550**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside reverse light does not work
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Centre exhaust is corroded

**MOT #14** 2018-09-29 10:32**MOT test number** 677364698693**Result** ✓ Passed**MOT #13** 2018-09-24 10:57**MOT test number** 917505236284**Result** ✗ Failed

- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Minor** Nearside Registration plate lamp throwing direct white light to the rear (4.7.1 (a))
- MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #12** 2016-10-11 15:14**MOT test number** 782600610352**Result** ✓ Passed**MOT #11** 2016-10-11 10:32**MOT test number** 503274479368**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tie bar/rod has excessive play in a ball joint (2.4.G.2)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #10** 2015-09-24 12:49**MOT test number** 125979181735**Result** ✓ Passed**MOT #9** 2015-09-24 09:33**MOT test number** 348405389507**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2014-09-30 16:21**MOT test number** 398203474459**Result** ✓ Passed**MOT #7** 2014-09-27 11:59**MOT test number** 775140474201**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #6	2013-09-28 09:04
MOT test number	535431973224
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5	2013-09-27 17:31
MOT test number	145960273249
Result	✓ Passed
Advice	Nearside Track rod end ball joint has slight play (2.2.B.1f)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)
Advice	Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4	2012-10-09 15:21
MOT test number	397483882455
Result	✓ Passed

MOT #3	2012-10-09 15:21
MOT test number	367643582444
Result	✗ Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)

MOT #2	2011-10-12 15:38
MOT test number	156775181209
Result	✓ Passed
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #1 2011-10-06 15:29

MOT test number 307429071249

Result ✗ Failed

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Fail** Power steering pump leaking from a failed joint (2.3.3b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
31 May 2024

<b>Tax status</b>	Valid until 1 March
-------------------	---------------------

<b>Days left</b>	307
------------------	-----

<b>MOT expiry date</b>	31 May 2024
------------------------	-------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-30
Last registration	2023-06-01
Complete history	<a href="#">See info</a>



Registration #1	2008-09-30	12 mi
Registration #2	2011-10-06	56.490 mi
Registration #3	2011-10-12	56.503 mi
Registration #4	2012-10-09	88.716 mi
Registration #5	2013-09-27	110.436 mi
Registration #6	2013-09-28	110.436 mi
Registration #7	2014-09-27	114.905 mi
Registration #8	2014-09-30	114.905 mi
Registration #9	2015-09-24	121.039 mi
Registration #10	2016-09-27	121.039 mi
Registration #11	2016-09-27	121.039 mi
Registration #12	2016-09-27	121.039 mi
Registration #13	2016-09-27	121.039 mi
Registration #14	2016-09-27	121.039 mi
Registration #15	2016-09-27	121.039 mi
Registration #16	2016-09-27	121.039 mi
Registration #17	2016-09-27	121.039 mi
Registration #18	2016-09-27	121.039 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1974 mm
Height	2067 mm
Length	4863 mm
Wheel base	2933 mm
Kerb weight	1710 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	8Y32525