



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE BLUE DRIVE
Colour	White
Year of manufacture	2016
Top speed	126 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	440 Nm at 2.750 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	46.3 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	H






Internet history

Entry 2

Date	2022-05-18
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2022-05-17
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-19
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	16
Total items failed	2

MOT #7	2023-06-20 14:00
MOT test number	112863990278
Result	✓ Passed
Next expiry date	2024-06-19
Advice	Offside Front Tyre worn close to legal limit/worn on edge 235/55/19 wearing inner edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 235/55/19 (3mm) (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing 235/55/19 (5.2.3 (d) (ii))

MOT #6	2023-06-20 08:27
MOT test number	714834674475
Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing 235/55/19 (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 235/55/19 wearing inner edge (5.2.3 (e))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 235/55/19 (3mm) (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #5** 2022-08-02 15:46**MOT test number** 589704874459**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2021-09-20 13:22**MOT test number** 790341556233**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2020-09-24 08:41**MOT test number** 468782639870**Result** ✓ Passed**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords In tread (5.2.3 (d) (i))**Advice** Nearside Rear Nail in tyre In inner band of tread**MOT #2** 2020-09-24 08:41**MOT test number** 382859826164**Result** ✗ Failed**Pass with rectification** Tyre pressure monitoring system malfunctioning or obviously inoperative Tyre pressures adjusted (5.2.3 (h))**Advice** Nearside Rear Nail in tyre In inner band of tread**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords In tread (5.2.3 (d) (i))



MOT #12019-09-18 10:36

MOT test number539001963316

Result

✓ Passed

- Advice

Offside Front Tyre worn close to legal limit/worn on edge Close to limit and bald on inner edge (5.2.3 (e))
- Advice

Front Items removed from driver's view prior to test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
19 June 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	19 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-16
Last registration	2023-06-20
Complete history	<a href="#">See info</a>



Registration #1	2016-09-16	14 mi
Registration #2	2019-09-18	37.761 mi
Registration #3	2020-09-24	46.313 mi
Registration #4	2020-09-24	46.313 mi
Registration #5	2021-09-20	48.656 mi
Registration #6	2022-09-20	50.000 mi
Registration #7	2022-09-20	50.000 mi
Registration #8	2022-09-20	50.000 mi
Registration #9	2022-09-20	50.000 mi
Registration #10	2023-06-20	51.000 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1880 mm
Height	1675 mm
Length	4700 mm
Wheel base	2700 mm
Kerb weight	2003 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	D4HBFU347475