



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	VELOSTER GDI SPORT
Colour	Silver
Year of manufacture	2012
Top speed	125 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	148 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-11
Pictures	20
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2024-06-26
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	37
Total items failed	2

MOT #15	2023-06-22 08:12
MOT test number	905272335693
Result	✓ Passed
Next expiry date	2024-06-26
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #14	2023-06-16 16:23
MOT test number	729006126809
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
MAJOR	Nearside Headlamp light intensity severely reduced (4.1.4 (a))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #13** 2022-06-27 14:32**MOT test number** 114923788386**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside dip beam light output intensity slightly reduced

**MOT #12** 2021-06-25 11:35**MOT test number** 677412483015**Result** ✓ Passed

- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Rear rake back plates corroded

**MOT #11** 2021-06-10 13:38**MOT test number** 251631447362**Result** ✗ Failed

- MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Windscreen washer not working (3.5 (a))

**MOT #10** 2020-06-04 14:37**MOT test number** 849150938841**Result** ✓ Passed**MOT #9** 2020-06-04 14:37**MOT test number** 427151429658**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #8** 2019-06-16 16:24**MOT test number** 422899544456**Result** ✓ Passed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-06-16 13:29**MOT test number** 499261117503**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Brake disc contaminated all (1.1.14 (b))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #6** 2018-12-05 17:45**MOT test number** 226611706946**Result** ✓ Passed

**MOT #5** 2018-12-04 11:35**MOT test number** 495268652922**Result** ✗ Failed

- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Nearside Rear Brake lever has restricted free movement calliper parking brake mech restricted movt (1.1.15 (e))
- MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

**MOT #4** 2017-08-16 14:28**MOT test number** 356907318752**Result** ✓ Passed**MOT #3** 2017-08-14 11:05**MOT test number** 759830274506**Result** ✗ Failed

- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #2** 2016-07-12 10:24**MOT test number** 303296200928**Result** ✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit 1.6mm (4.1.E.1)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit 2.0mm (4.1.E.1)

**MOT #1** 2015-05-15 11:25**MOT test number** 349265535163**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
26 June 2024

Tax status		Valid until 1 October
Days left		156
MOT expiry date		26 June 2024
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-04-30
Last registration	2023-06-22
Complete history	<a href="#">See info</a>



Registration #1	2012-04-30	23 mi
Registration #2	2015-05-15	8.594 mi
Registration #3	2016-07-12	24.132 mi
Registration #4	2017-08-14	46.153 mi
Registration #5	2017-08-16	46.177 mi
Registration #6	2018-12-04	72.147 mi
Registration #7	2018-12-05	72.147 mi
Registration #8	2019-06-16	84.139 mi
Registration #9	2019-06-16	84.142 mi
Registration #10	2019-06-16	84.142 mi
Registration #11	2019-06-16	84.142 mi
Registration #12	2019-06-16	84.142 mi
Registration #13	2019-06-16	84.142 mi
Registration #14	2019-06-16	84.142 mi
Registration #15	2019-06-16	84.142 mi
Registration #16	2019-06-16	84.142 mi
Registration #17	2019-06-16	84.142 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	49%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1790 mm
Height	1399 mm
Length	4220 mm
Wheel base	2650 mm
Kerb weight	1236 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4

Number of axles	2
Engine number	G4FDCU776384