



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK200K ELEGANCE
Colour	Silver
Year of manufacture	2007
Top speed	147 mph
0 - 60 mph	9.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	200 g/km
CO2 label	J





Internet history

Entry 3

Date 2024-02-08

Pictures 34

Listing price [View report](#)



source: [cargurus.co.uk](#)

Entry 2

Date 2021-07-09

Pictures 12

Listing price [View report](#)




source: [cargurus.co.uk](#)

Entry 1

Date 2021-07-07

Pictures 20

Listing price [View report](#)



source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-10-02
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	29
Total items failed	8

MOT #20 2023-10-03 08:11**MOT test number** 460129220280**Result** Passed**Next expiry date** 2024-10-02**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive Gearbox (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #19** 2022-09-23 09:04**MOT test number** 108146544827**Result** Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #18** 2021-09-27 11:46**MOT test number** 753733670940**Result** Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material of front to rear (1.1.11 (c))

**MOT #17** 2021-09-27 09:02**MOT test number** 608223905513**Result** ✗ Failed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material of front to rear (1.1.11 (c))**Fail** Offside Front Lower Suspension arm ball joint excessively worn rear arm (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #16** 2020-09-29 10:01**MOT test number** 854388488439**Result** ✓ Passed**MOT #15** 2019-10-03 09:41**MOT test number** 732505485959**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2019-10-02 09:28**MOT test number** 481013928217**Result** ✗ Failed**Fail** Offside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2018-07-18 10:04**MOT test number** 657274821165**Result** ✓ Passed**Advice** Oil leaks underneath

**MOT #12** 2018-07-16 15:04**MOT test number** 663822780923**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #11** 2017-07-29 10:29**MOT test number** 357803439413**Result** ✓ Passed**MOT #10** 2016-07-29 08:42**MOT test number** 780610297136**Result** ✓ Passed**Advice** Oil leak**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2016-07-29 08:42**MOT test number** 941887860250**Result** ✗ Failed**Advice** Oil leak**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2015-07-29 14:00**MOT test number** 789710615208**Result** ✓ Passed**Notice** Oil leak**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2014-07-28 10:47**MOT test number** 716579904233**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside & offside front tyre sidewalls deteriorated**MOT #6** 2013-07-31 13:50**MOT test number** 548472113261**Result** ✓ Passed**Notice** Nearside front tyre sidewall damaged**MOT #5** 2013-07-31 09:46**MOT test number** 147532113296**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Nearside front tyre sidewall damaged

**MOT #4** 2012-07-18 14:14**MOT test number** 458560602286**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-07-18 10:18**MOT test number** 295520702244**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #2** 2011-07-21 10:25**MOT test number** 219832701294**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2010-07-29 12:57**MOT test number** 212450710253**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
2 October 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	2 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-07-31
Last registration	2023-10-03
Complete history	See info



Registration #1	2007-07-31	6 mi
Registration #2	2010-07-29	21.246 mi
Registration #3	2011-07-21	26.746 mi
Registration #4	2012-07-18	31.860 mi
Registration #5	2012-07-18	31.860 mi
Registration #6	2013-07-31	37.079 mi
Registration #7	2013-07-31	37.079 mi
Registration #8	2014-07-28	41.755 mi
Registration #9	2015-07-29	44.301 mi
Registration #10	2016-07-29	49.899 mi
Registration #11	2016-07-29	49.899 mi
Registration #12	2017-07-29	54.051 mi
Registration #13	2018-07-29	55.000 mi
Registration #14	2019-07-29	55.000 mi
Registration #15	2020-07-29	55.000 mi
Registration #16	2021-07-29	55.000 mi
Registration #17	2022-07-29	55.000 mi
Registration #18	2023-07-29	55.000 mi
Registration #19	2024-07-29	55.000 mi
Registration #20	2025-07-29	55.000 mi
Registration #21	2026-07-29	55.000 mi
Registration #22	2027-07-29	55.000 mi
Registration #23	2028-07-29	55.000 mi
Registration #24	2029-07-29	55.000 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1540 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195531010518