





report date: 2024-03-28

General information

Make	AUDI
Model	S3 S3 TFSI QUATTRO
Colour	Blue
Year of manufacture	2008
Top speed	155 mph
0 - 60 mph	5.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	265 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.984 сс
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	39.2 mpg
Consumption combined	31.0 mpg
CO2 emission	217 g/km
CO2 label	K



CarCheck.co.uk page 1/14



Internet history


Entry 1


Date 2021-10-20

Pictures 23

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2025-02-14
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	29
Total items failed	9

MOT #19	2024-02-15 10:28
MOT test number	894452426381
Result	✓ Passed
Next expiry date	2025-02-14

MOT #18		2022-11-17 15:37
MOT test	number	413304763854
Result		✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear corroded	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #17	2021-11-19 10:08
MOT test number	571410065102
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/14



(i))

Advice

Inner (5.3.4 (a) (i))

AVOSYJY report date: 2024-03-28

MOT test number

613145778949

Result

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Inner (5.3.4 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)

MOT #15	2020-10-14 07:55
MOT test number	546711980890
Result	✓ Passed

Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement

MOT #14	2019-04-04 16:07
MOT test number	705902441716
Result	✓ Passed

MOT #13	2018-08-10 12:31
MOT test number	932214169935
Result	✓ Passed

MOT #12	2018-08-10 10:50
MOT test number	655328824308
Result	X Failed
Fail Offside Rear Service brake grabbing severely (1.2.1 (c))	

CarCheck.co.uk page 4/14



 MOT #11
 2017-08-16 10:22

 MOT test number
 703120424890

 Result
 ✓ Passed

Advice Offside Front brake noisy when turning left

Advice Rear brakes noisy

MOT #10

MOT test number

Fesult

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Registration plate lamp not working (1.1.C.1d)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8

MOT test number

237867729627

Result

Advice Under trays fitted

2015-07-22 15:35

Advice Under trays fitted

CarCheck.co.uk page 5/14



MOT test number

Result

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Under trays fitted

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

2014-05-20 09:43 **MOT #6 MOT** test number 758750244103 Result ✓ Passed **Notice** Under-trays fitted obscuring some underside components Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Notice Nail in nearside rear tyre Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Notice Rear tyres cracking around edges Offside Front Brake pad(s) wearing thin (3.5.1g) Advice Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5		2013-05-27 12:22
MOT test	number	759447943118
Result		✓ Passed
Notice	Oil low	
Notice	Nail in nearside rear tyre	
Notice	Vacumm pipe at engine damaged	

CarCheck.co.uk page 6/14



MOT #4 2012-05-25 14:51 **MOT** test number 597066742187 Result ✓ Passed MOT #3 2012-05-25 09:39 **MOT test number** 149366542196 Result × Failed Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Notice** Engine oil low Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #2
 2011-05-26 14:26

 MOT test number
 105976941134

 Result
 ✓ Passed

 MOT #1
 2011-05-26 12:20

 MOT test number
 456806241189

 Result
 X Failed

 Fail

 Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



\sim		
Owner	hictory	7
OWITCE	HIJLOH	٧

For how long did the current and previous owner(s) have this AUDI? How many owners defined the premium report and see all owner registrations. Download the full report	
HARMAN AND AND AND AND AND AND AND AND AND A	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-05-29
Last registration	2024-02-15
Complete history	See info



Registration #1	2008-05-29	23 mi
Registration #2	2011-05-26	16.704 mi
Registration #3	2011-05-26	16.710 mi
Registration #4	2012-05-25	23.355 mi
Registration #5	2012-05-25	23.360 mi
Registration #6	2013-05-27	30.136 mi
Registration #7	2014-05-20	35.790 mi
Registration #8	2015-07-22	49.246 mi
Registration #9	2015-07-22	49.246 mi
Registration #10	2016-08-03	59.782 mi
Registration #11	2016-08-03	59.784 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11,177 66

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1399 mm
Length	4214 mm
Wheel base	2578 mm
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles CarCheck.co.uk	2 page 14/14

Engine number

BHZ 010999