




General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Silver
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





MOT history

MOT expiry date	2024-10-19
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	20
Total items failed	6

MOT #16	2023-10-20 08:31
MOT test number	176416342754
Result	✓ Passed
Next expiry date	2024-10-19
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15	2022-10-20 18:07
MOT test number	252520963068
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14** 2022-10-20 18:07**MOT test number** 274726011231**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (4.1.2 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (4.1.2 (a))**MOT #13** 2021-10-19 16:59**MOT test number** 174230961276**Result** ✓ Passed**MOT #12** 2020-10-19 08:46**MOT test number** 807351209900**Result** ✓ Passed**MOT #11** 2019-10-16 08:46**MOT test number** 310357269604**Result** ✓ Passed**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Advice** Both rear tyres tread cracks noted**MOT #10** 2018-10-17 14:22**MOT test number** 545971227493**Result** ✓ Passed

**MOT #9** 2018-10-17 08:47**MOT test number** 643210447458**Result** ✗ Failed**MAJOR** Rear Registration plate does not conform to the specified requirements (0.1 (d))**MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #8** 2017-09-27 08:33**MOT test number** 632727343063**Result** ✓ Passed**MOT #7** 2016-10-06 13:27**MOT test number** 331227250263**Result** ✓ Passed**MOT #6** 2016-10-06 08:39**MOT test number** 197199647423**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #5** 2015-10-12 14:07**MOT test number** 748784139733**Result** ✓ Passed**Advice** N/s/r tyre nail in tread**MOT #4** 2014-10-15 10:16**MOT test number** 497788384293**Result** ✓ Passed**Notice** Front tyres wearing on edges



MOT #3	2013-10-09 14:24
MOT test number	356222983279
Result	✓ Passed

MOT #2	2013-10-09 10:10
MOT test number	837812283224
Result	✗ Failed
<div><div>Fail</div>Windscreen washer provides insufficient washer liquid (8.2.3)</div> <div><div>Fail</div>Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)</div> <div><div>Fail</div>Nearside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)</div>	

MOT #1	2012-05-22 17:23
MOT test number	278903442409
Result	✓ Passed
<div><div>Advice</div>Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)</div> <div><div>Notice</div>Front screen marked</div> <div><div>Advice</div>Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)</div> <div><div>Notice</div>Front wipers poor</div> <div><div>Notice</div>Offside front inner arch hitting spring slightly</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
19 October 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-09
Last registration	2023-10-20
Complete history	See info



Registration #1	2009-06-09	24 mi
Registration #2	2012-05-22	17.721 mi
Registration #3	2013-10-09	23.552 mi
Registration #4	2013-10-09	23.552 mi
Registration #5	2014-10-15	27.331 mi
Registration #6	2015-10-12	31.609 mi
Registration #7	2016-10-06	35.244 mi
Registration #8	2016-10-06	35.244 mi
Registration #9	2017-09-27	38.177 mi
Registration #10	2018-05-22	38.177 mi
Registration #11	2019-05-22	38.177 mi
Registration #12	2020-05-22	38.177 mi
Registration #13	2021-05-22	38.177 mi
Registration #14	2022-05-22	38.177 mi
Registration #15	2023-05-22	38.177 mi
Registration #16	2023-10-20	38.177 mi
Registration #17	2023-10-20	38.177 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9B03425