



HYUNDAI



DU610HS


report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Grey
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-17
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	17
Total items failed	7

MOT #14	2023-05-18 08:24
MOT test number	733628940828
Result	✓ Passed
Next expiry date	2024-05-17
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Brake pipe corroded, covered in grease or other material all (1.1.11 (c))

MOT #13	2022-09-13 15:28
MOT test number	166227735157
Result	✓ Passed
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #12**

2022-09-13 09:57

MOT test number

138986679524

Result**✗ Failed**

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11

2021-12-28 08:46

MOT test number

787870904341

Result**✓ Passed**

Advice Nearside Rear Coil spring corroded and offside (5.3.1 (b) (i))

MOT #10

2020-12-23 17:22

MOT test number

453360963401

Result**✓ Passed**

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension component ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear tyre wearing uneven on inner edge

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #9

2019-07-24 16:22

MOT test number

682168685556

Result**✓ Passed**

**MOT #8** 2019-07-23 13:06**MOT test number** 908555801382**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Side repeater not working mirror led (4.4.1 (a) (ii))**MOT #7** 2018-06-27 16:06**MOT test number** 521882973665**Result** ✓ Passed**MOT #6** 2017-07-06 15:56**MOT test number** 891548821019**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2017-07-06 09:00**MOT test number** 527923668536**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-06-28 09:58**MOT test number** 277923125242**Result** ✓ Passed

**MOT #3** 2016-06-22 13:56**MOT test number** 666533074183**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #2** 2015-07-21 17:21**MOT test number** 257622105228**Result** ✓ Passed**Advice** Offside Front suspension has slight play in an outer ball joint (2.5.B.2a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-07-22 11:55**MOT test number** 336853004253**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
17 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	17 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-10-07
Last registration	2023-05-18
Complete history	See info



Registration #1	2011-10-07	9 mi
Registration #2	2014-07-22	49.255 mi
Registration #3	2015-07-21	62.759 mi
Registration #4	2016-06-22	82.711 mi
Registration #5	2016-06-28	83.399 mi
Registration #6	2017-07-06	100.848 mi
Registration #7	2017-07-06	100.856 mi
Registration #8	2018-06-27	106.627 mi
Registration #9	2019-05-20	151.277 mi
Registration #10	2019-05-20	151.277 mi
Registration #11	2019-05-20	151.277 mi
Registration #12	2019-05-20	151.277 mi
Registration #13	2019-05-20	151.277 mi
Registration #14	2019-05-20	151.277 mi
Registration #15	2019-05-20	151.277 mi
Registration #16	2019-05-20	151.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1987 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4HBBU451177