






report date: 2024-03-29

### General information

Make	FORD
Model	FIESTA BASE TDCI
Colour	White
Year of manufacture	2010
Top speed	100 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-29

## MOT history

MOT expiry date	2024-06-04
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	11
Total items failed	9

MOT #14	2023-06-05 15:47
MOT test number	333238840789
Result	✓ Passed
Next expiry date	2024-06-04

MOT #13	2022-05-25 11:48
MOT test number	932754057927
Result	✓ Passed
Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	

MOT #12		2022-05-24 12:10
MOT test number		612587202870
Result		<b>X</b> Failed
Advice Offside Front Whe	el bearing slightly noisy (5.1.3 (b) (i))	
Fail Nearside Front Tyre t	read depth below requirements of 1.6r	mm (5.2.3 (e))
Fail Offside Front Tyre ha	s a tear, caused by separation or partic	al failure of its structure inside wall (5.2.3

MOT #11	2021-04-28 07:48
MOT test number	621199399618
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT #10

MOT test number

Result

Advice Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

MOT test number

522287560209

Result

Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

Fail Nearside Front Tyre has ply or cords exposed 195/50 15 (5.2.3 (d) (ii))

MOT test number

S52104677926

Result

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Slight Noise From Offside Drive Shaft Bearing

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Slight Play In Steering Column Universal Joints

 MOT #7
 2018-04-27 09:45

 MOT test number
 493709848475

 Result
 ✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #6 2018-04-26 11:28 MOT test number 555467993445

Result × Failed

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #5** 2016-08-31 12:13

MOT test number 369164492082

Result \square Passed

**Advice** Nearside Rear Road wheel slightly damaged (4.2.A.1a)

MOT #4 2015-09-18 15:12

**MOT test number** 873167766973

**Result** ✓ Passed

MOT #3 2015-09-18 14:00

**MOT test number** 555786775715

**Result** X Failed

Fail Offside Side repeater insecure (1.4.A.2b)

**Fail** Offside Body has a sharp edge caused by damage door mirror assembly (6.1.C.1)

MOT #2 2014-09-05 11:31

**MOT test number** 997718044281

**Result** ✓ Passed

**MOT #1** 2013-09-05 08:57

MOT test number 115788243283

Result 

Passed

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Days left 336

MOT expiry date 4 June 2024

Full MOT history See MOT history

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

For how long did the current and previous owner(s) have this FORD? How many owners defined the current and see all owner registrations. Download the full report in the premium report and see all owner registrations.	
manage of the same	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	IK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-20
Last registration	2023-06-05
Complete history	See info



Registration #1	2010-09-20	14 mi
Registration #2	2013-09-05	9.209 mi
Registration #3	2014-09-05	13.092 mi
Registration #4	2015-09-18	22.569 mi
Registration #5	2015-09-18	22.569 mi
Registration #6	2016-08-31	22.736 mi
Registration #7	2018-04-26	33.663 mi
Registration #8	2018-04-27	33.663 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

## Safety ratings

NCAP rating	****
Video	see crash video



### Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	AM25060

CarCheck.co.uk page 11/11