





report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM
Colour	Grey
Year of manufacture	2009
Top speed	121 mph
0 - 60 mph	9.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/12



report date: 2024-03-28

MOT histor	`\/
1401 1113101	У

MOT expiry date	2025-02-22
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	15
Total items failed	8

MOT #18	2024-02-21 12:52
MOT test number	866445021611
Result	✓ Passed
Next expiry date	2025-02-22

MOT #17	2023-02-23 17:17
MOT test number	501125194242
Result	✓ Passed

MOT #16		2023-02-23 17:17
MOT test number		888412908527
Result		X Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT #15 2023-02-21 13:08 **MOT** test number 338646217365 Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) Fail Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Fail Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail

MOT #14		2022-02-16 10:21
MOT test	number	613320834600
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2021-02-19 09:23
MOT test number	597440871603
Result	✓ Passed
MOT #12	2020-01-28 12:18
MOT test number	768047685054
Result	✓ Passed
Advice Front exhaust flexi deteriorated	

CarCheck.co.uk page 3/12



report date: 2024-03-28

2018-01-18 10:41

MOT test number

Result

Fail Offside Front Driver's seat insecure (6.2.5 (a) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Front exhaust flexi deteriorated

MOT test number

Result

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (iii))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOI #9	2010-01-10 10.41
MOT test number	747804017743
Result	✓ Passed
MOT #8	2017-01-17 11:42
MOT test number	592333412787
Result	✓ Passed
Advice Rear tyres wearing inner edges.	
Advice Nearside Rear tyre beginning to misshape.	
Advice Front tyres wearing inner and outer edges.	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #7 2016-01-29 10:07

MOT test number 671265550458

MOT #6 2015-01-20 09:23

MOT test number 397190225017

Result ✓ Passed

MOT #5 2014-01-08 10:41

MOT test number 607788404086

Result
✓ Passed

MOT #4 2014-01-07 12:22

MOT test number 257517904011

Result X Failed

Fail Bonnet cannot be secured in the closed position (8.4.1)

MOT #3 2013-01-18 11:47

MOT test number 189778213480

Result ✓ Passed

MOT #2 2012-02-06 09:47

MOT test number 347007432022

Result ✓ Passed

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

MOT #1 2011-09-20 10:12

MOT test number 788293161205

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners defined the current and see all owner registrations. Download the full report in the premium report and see all owner registrations.	
manners and the same of the sa	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Flate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-16
Last registration	2024-02-21
Complete history	See info



Registration #1	2009-03-16	10 mi
Registration #2	2011-09-20	14.952 mi
Registration #3	2012-02-06	18.080 mi
Registration #4	2013-01-18	25.720 mi
Registration #5	2014-01-07	33.969 mi
Registration #6	2014-01-08	33.969 mi
Registration #7	2015-01-20	40.729 mi
Registration #8	2016-01-29	48.682 mi
Registration #9	2017-01-17	54.616 mi
Registration #10	2018-01-18	61.221 mi
Registration #11		10.107 au
Registration #12		11.777 46
		77.777 es
Registration #12		11.777 es 11.777 es 11.777 es
Registration #12 Registration #13		11.777 es 11.777 es 11.777 es 11.777 es
Registration #12 Registration #13 Registration #14		11.777 es 21.777 es 21.777 es 21.777 es
Registration #12 Registration #13 Registration #14 Registration #15		11 177 46 21 177 46 21 177 46 21 177 46 21 177 46
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1326 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 9B33524