



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Silver
Year of manufacture	2007
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	99 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	130 g/km
CO2 label	D





MOT history

MOT expiry date	2025-01-11
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	23
Total items failed	10

MOT #17 2024-01-12 12:26

MOT test number 109466449946

Result ✓ Passed

Next expiry date 2025-01-11

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 29% imbalance across rear axle (1.2.1 (b) (i))

Advice Front Play in steering rack inner joint(s) both

MOT #16 2023-06-06 18:20

MOT test number 639770500245

Result ✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #15**

2023-06-06 11:26

MOT test number

396047725447

Result

✗ Failed

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #14**

2022-06-08 14:22

MOT test number

419849901678

Result

✓ Passed

Advice Suspension arm ball joint has slight play osf (5.3.4 (a) (i))**MOT #13**

2021-06-03 11:23

MOT test number

689932262227

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))**Advice** Subframe mounting prescribed area is corroded but not considered excessive Front subframe corroded (5.3.6 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))

**MOT #12** 2020-06-11 09:23**MOT test number** 554275834421**Result** ✓ Passed**Advice** 2 front wishbones corroded**MOT #11** 2020-06-09 15:13**MOT test number** 945302699678**Result** ✗ Failed**Advice** 2 front wishbones corroded**Fail** Nearside Rear Brake pipe excessively corroded x2 (1.1.11 (c))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Tyre slightly damaged/cracking or perishing 2 rear tyres perished (5.2.3 (d) (ii))**MOT #10** 2019-04-15 11:35**MOT test number** 316180182613**Result** ✓ Passed**Advice** 4 tyres small cracks ...perished**MOT #9** 2018-04-06 09:36**MOT test number** 417774818223**Result** ✓ Passed**Advice** Brake pipe slightly corroded both rear (3.6.B.2c)**MOT #8** 2017-04-13 08:40**MOT test number** 246430595644**Result** ✓ Passed

**MOT #7** 2016-04-11 08:56**MOT test number** 430161740804**Result** ✓ Passed**MOT #6** 2015-04-15 15:13**MOT test number** 969265905102**Result** ✓ Passed**MOT #5** 2013-12-19 10:37**MOT test number** 615603353334**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Oil leak**MOT #4** 2012-12-13 09:35**MOT test number** 739548142333**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-12-15 15:50**MOT test number** 785419341316**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-12-31 12:07**MOT test number** 301125660343**Result** ✓ Passed



MOT #1	2010-12-31 09:14
MOT test number	203585260359
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
11 January 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-27
Last registration	2024-01-12
Complete history	See info



Registration #1	2007-09-27	13 mi
Registration #2	2010-12-31	11.007 mi
Registration #3	2010-12-31	11.007 mi
Registration #4	2011-12-15	12.880 mi
Registration #5	2012-12-13	14.076 mi
Registration #6	2013-12-19	15.322 mi
Registration #7	2015-04-15	16.539 mi
Registration #8	2016-04-11	16.883 mi
Registration #9	2017-04-13	17.990 mi
Registration #10	2018-04-13	18.337 mi
Registration #11	2018-04-13	18.337 mi
Registration #12	2018-04-13	18.337 mi
Registration #13	2018-04-13	18.337 mi
Registration #14	2018-04-13	18.337 mi
Registration #15	2018-04-13	18.337 mi
Registration #16	2018-04-13	18.337 mi
Registration #17	2018-04-13	18.337 mi
Registration #18	2018-04-13	18.337 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4HG7275469