



report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 SZ4
Colour	Red
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-17
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	25
Total items failed	2

MOT #11	2023-12-22 07:52
MOT test number	193559051530
Result	✓ Passed
Next expiry date	2025-01-17
Advice	Rear Sub-frame corroded but not seriously weakened SUSPENSION COMPONENTS CORRODED (5.3.3 (b) (i))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Sub-frame corroded but not seriously weakened SUSPENSION COMPONENTS CORRODED (5.3.3 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #10** 2023-01-18 09:46**MOT test number** 767229758012**Result** ✓ Passed

- Advice** Rear axel corroded
- Advice** Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Advice** General surface rust on suspension and chassis
- Advice** Front Suspension arm corroded but not seriously weakened Nearside and Offside (5.3.3 (b) (i))

MOT #9 2023-01-18 08:47**MOT test number** 757176174108**Result** ✗ Failed

- Advice** Front Suspension arm corroded but not seriously weakened Nearside and Offside (5.3.3 (b) (i))
- Fail** Rear Road wheel fixing missing Nearside and Offside (5.2.1 (a) (i))
- Advice** General surface rust on suspension and chassis
- Advice** Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Fail** Front Road wheel fixing missing Nearside and Offside (5.2.1 (a) (i))
- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Advice** Rear axel corroded

MOT #8 2021-11-05 11:01**MOT test number** 632835607815**Result** ✓ Passed

**MOT #7** 2020-01-13 09:05**MOT test number** 794357820177**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #6** 2019-01-11 10:48**MOT test number** 225893919055**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #5** 2018-01-20 09:30**MOT test number** 426071849993**Result** ✓ Passed**MOT #4** 2017-01-21 08:58**MOT test number** 702554383175**Result** ✓ Passed**MOT #3** 2016-01-23 09:30**MOT test number** 462447821426**Result** ✓ Passed



MOT #2	2015-01-24 10:34
MOT test number	398414725098
Result	✓ Passed
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
Notice	N/s/f wishbone rear bush slightly deteriorated
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
Notice	O/s/f wishbone rear bush slightly deteriorated

MOT #1	2014-01-31 15:14
MOT test number	939491634031
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
17 January 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-05-17
Last registration	2023-12-22
Complete history	See info



Registration #1	2010-05-17	10 mi
Registration #2	2014-01-31	41.076 mi
Registration #3	2015-01-24	54.176 mi
Registration #4	2016-01-23	66.710 mi
Registration #5	2017-01-21	78.843 mi
Registration #6	2018-01-20	87.507 mi
Registration #7	2019-01-11	93.615 mi
Registration #8	2020-05-20	95.277 mi
Registration #9	2021-05-20	95.277 mi
Registration #10	2022-05-20	95.277 mi
Registration #11	2023-05-20	95.277 mi
Registration #12	2024-05-20	95.277 mi
Registration #13	2025-05-20	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1605 mm
Length	4255 mm
Wheel base	2500 mm
Kerb weight	1140 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1490340