



report date: 2024-03-28

General information

Make	MINI
Model	ONE
Colour	Green
Year of manufacture	2016
Top speed	121 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	180 Nm at 1.400 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-14
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-05-31
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	14
Total items failed	0

MOT #5	2023-05-24 10:19
MOT test number	531026408434
Result	✓ Passed
Next expiry date	2024-05-31
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4	2022-05-27 10:11
MOT test number	116492347117
Result	✓ Passed
Advice	Offside rear tyre worn close to legal limit/worn on edge/slightly damaged/cracking or perishing (1756515)
Advice	Nearside rear tyre worn close to legal limit/worn on edge/slightly damaged/cracking or perishing (1756515)

MOT #3	2021-05-24 14:40
MOT test number	118066051138
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #2** 2021-05-24 13:22**MOT test number** 487120186566**Result** ✗ Failed**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**DANGEROUS** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #1** 2020-06-01 15:12**MOT test number** 816792130126**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Tyre slightly damaged/cracking or perishing both front on inside (5.2.3 (d) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
31 May 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	31 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2016-06-25
Last registration	2023-05-24
Complete history	See info



Registration #1	2016-06-25	27 mi
Registration #2	2020-06-01	45.988 mi
Registration #3	2021-05-24	49.543 mi
Registration #4	2021-05-24	49.543 mi
Registration #5	2023-05-24	49.543 mi
Registration #6	2023-05-24	49.543 mi
Registration #7	2023-05-24	49.543 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3821 mm
Wheel base	2495 mm
Kerb weight	1090 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number	F875H202
---------------	----------