





report date: 2024-03-28

General information

Make	CITROEN
Model	C2 HDI SX
Colour	Blue
Year of manufacture	2004
Top speed	103 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	150 Nm at 1.750 rpm
Engine capacity	1.398 сс
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	В



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 1

Date	2021-12-02
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

MOT expiry date	2023-12-07
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	18
Total items failed	23

MOT #22		2022-11-29 11:59
MOT test	number	569549160078
Result		✓ Passed
Next expi	ry date	2023-12-07
Advice	Chassis, suspension components, sub frame, rear axle, brakes and fuel lines corroc	led
Advice Exhaust emits black smoke during acceleration (8.2.1.2 (g))		
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

4OT #21	2022-11-18 17:48
NOT test number	954999622157
Result	🗙 Failed
Fail Nearside Front Headlamp insecure (4.1.1 (c))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Exhaust emits black smoke during acceleration (8.2.1.2 (g))	
Advice Chassis, suspension components, sub frame, rear axle, brakes and fuel lines co	orroded
Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))	

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #20 2021-12-08 13:47

MOT test number 300211787333

Result ✓ Passed

Advice Exhaust emits black smoke during acceleration (8.2.1.2 (g))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19 2021-12-07 12:24

MOT test number 595004262287

Result X Failed

Fail Exhaust emits clearly visible black smoke during acceleration (8.2.1.2 (g))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail Emissions not tested Excessive black smoke during acceleration (8.2.2.2 (e))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #18 2021-11-17 12:51 **MOT** test number 846577868838 Result × Failed **Advice** Offside Front Sub-frame ball joint has slight play (5.3.4 (a) (i)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Service brake efficiency below requirements (1.2.2 (a) (i)) Nearside Front Headlamp insecure (4.1.1 (c)) Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) Fail Fail Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i)) Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Nearside Front Headlamp aim too low (4.1.2 (a)) Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth Fail required is 1.0mm (5.2.3 (e))

MOT #17	2020-11-19 14:30
MOT test number	574197530737
Pocult	/ Passad

MOT #16

MOT test number

866503345107

Result

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT test number

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

MOT test number

Result

MOT #13

MOT test number

2018-06-07 14:07

871341441887

✓ Passed

MOT #13

MOT test number

138464681270

Result

Advice

Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

 MOT #12
 2016-05-10 09:08

 MOT test number
 573344888121

 Result
 ✓ Passed

MOT #11

MOT test number

Result

Pass with rectification

Nearside Front Headlamp not working on dipped beam (1.7.5a)

MOT #10

MOT test number

Passed

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 6/15



MOT #3

Result

MOT test number

PG04UCX

report date: 2024-03-28

2009-07-20 16:32

231021809271

✓ Passed

MOT #9	2014-06-11 16:45
MOT test number	337312264151
Result	✓ Passed
MOT #8	2013-07-09 09:44
MOT test number	297650193442
Result	✓ Passed
MOT #7	2012-07-16 14:50
MOT test number	655718592132
Result	✓ Passed
MOT #6	2011-07-08 11:39
MOT test number	418399481119
Result	✓ Passed
MOT #5	2010-07-06 11:08
MOT test number	764297280175
Result	★ Failed
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
MOT #4	2010-07-06 11:08
MOT test number	632107180192
Result	✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #2	2008-07-22 10:55
MOT test number	254844508215
Result	✓ Passed
MOT #1	2007-07-12 08:53
MOT test number	262223397455
Result	✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	7 December 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



factor scincore

PG04UCX

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this CITROEN had different number plates. about of pliates

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-07-31
Last registration	2022-11-29
Complete history	See info



Registration #1	2004-07-31	17 mi
Registration #2	2007-07-12	14.932 mi
Registration #3	2008-07-22	18.094 mi
Registration #4	2009-07-20	20.757 mi
Registration #5	2010-07-06	22.083 mi
Registration #6	2011-07-08	24.685 mi
Registration #7	2012-07-16	26.709 mi
Registration #8	2013-07-09	28.134 mi
Registration #9	2014-06-11	29.414 mi
Registration #10	2015-05-14	40.353 mi
Registration #11	2016-05-10	50.803 mi
Registration #12	2016-05-10	50.803 mi
negistration # 22	2010 05 10	3010031111
Registration #13	2010 03 10	11.771 66
		11.77 mi
Registration #13		11.777 esc 11.777 esc 11.777 esc
Registration #13 Registration #14		11.770 mi 11.770 mi 11.770 mi
Registration #13 Registration #14 Registration #15		11.770 mi 11.770 mi 11.770 mi 11.770 mi
Registration #13 Registration #14 Registration #15 Registration #16		11.00 mi 11.00 mi 11.00 mi 11.00 mi 11.00 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		11.00 mi 11.00 mi 11.00 mi 11.00 mi 11.00 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-28

Safety ratings

NCAP rating	***
-------------	-----

Video <u>see crash video</u>



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	996 kg
Max. allowed weight	1390 kg

Additional information

Fuel tank capacity	41
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FD600894567

CarCheck.co.uk page 15/15