




report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg






Internet history

Entry 1

Date	2021-09-15
Pictures	11
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #17	2021-09-21 15:57
MOT test number	226816225149
Result	✓ Passed
Next expiry date	2022-10-07
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16	2021-09-21 14:51
MOT test number	288544912481
Result	✗ Failed
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #15	2020-10-08 14:42
MOT test number	925758524199
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Brake fluid close to minimum mark (1.1.10 (d) (ii))
Advice	Oil leak
Advice	Nearside Front Tyre worn close to legal limit/worn on edge wearing on both edges tyre is also perished (5.2.3 (e))
Advice	Offside Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))

**MOT #14**

2020-10-08 11:29

MOT test number

330355348886

Result**✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing tyre is cracked and perished (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on both edges tyre is also perished (5.2.3 (e))**Advice** Offside Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** Oil leak**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm inside edge (5.2.3 (e))**MOT #13**

2019-04-05 15:57

MOT test number

579112717330

Result**✓ Passed****Advice** Brake pipe corroded, covered in grease or other material x4 (1.1.11 (c))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12**

2019-04-01 15:56

MOT test number

411528368112

Result**✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material x4 (1.1.11 (c))
- Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Fail** Steering wheel has excessive movement up and down (2.2.2 (a))
- Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #11

2018-03-27 10:03

MOT test number

306243404015

Result**✓ Passed**

- Advice** Offside rear brake sticking slightly
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside front tyre bald on edges

MOT #10

2018-03-20 11:35

MOT test number

286656778436

Result**✗ Failed**

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside rear brake sticking slightly
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Advice** Offside front tyre bald on edges
- Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)

**MOT #9** 2017-03-28 10:02**MOT test number** 184192691843**Result** ✓ Passed**Advice** Slight play at steering column**MOT #8** 2016-03-28 10:39**MOT test number** 628984833041**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened heat damaged (3.5.1i)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Rear rear brake fluctuating, but not excessively (3.7.B.3)**MOT #7** 2016-03-26 13:11**MOT test number** 751733521659**Result** ✗ Failed**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Rear rear brake fluctuating, but not excessively (3.7.B.3)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened heat damaged (3.5.1i)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #6** 2015-03-21 09:50**MOT test number** 898900885067**Result** ✓ Passed**MOT #5** 2014-03-23 11:14**MOT test number** 298882984060**Result** ✓ Passed

**MOT #4** 2013-03-23 11:23**MOT test number** 265202283004**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear exhaust mount snapped**MOT #3** 2012-03-24 14:41**MOT test number** 308244582055**Result** ✓ Passed**MOT #2** 2011-03-26 12:17**MOT test number** 966735881014**Result** ✓ Passed**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyres tread slightly distorted**MOT #1** 2011-03-26 11:56**MOT test number** 855235281074**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyres tread slightly distorted**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-31
Last registration	2021-09-21
Complete history	See info



Registration #1	2008-03-31	9 mi
Registration #2	2011-03-26	26.686 mi
Registration #3	2011-03-26	26.686 mi
Registration #4	2012-03-24	33.279 mi
Registration #5	2013-03-23	38.644 mi
Registration #6	2014-03-23	43.923 mi
Registration #7	2015-03-21	48.924 mi
Registration #8	2016-03-26	53.300 mi
Registration #9	2016-03-28	53.313 mi
Registration #10	2017-03-28	56.616 mi
Registration #11	2018-03-28	59.919 mi
Registration #12	2019-03-28	63.222 mi
Registration #13	2020-03-28	66.525 mi
Registration #14	2021-03-28	69.828 mi
Registration #15	2022-03-28	73.131 mi
Registration #16	2023-03-28	76.434 mi
Registration #17	2024-03-28	79.737 mi
Registration #18	2025-03-28	83.040 mi
Registration #19	2026-03-28	86.343 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564