





report date: 2024-03-29

General information

Make	ТОУОТА
Model	C-HR DYNAMIC
Colour	Grey
Year of manufacture	2018
Top speed	105 mph
0 - 60 mph	11.0 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	122 BHP
Max. torque	142 Nm at 4.000 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	83.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	74.3 mpg
CO2 emission	87 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 3

Date 2021-06-29

Pictures 20

Listing price <u>View report</u>









source: heycar.co.uk

Entry 2

Date	2021-06-16	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

Entry 1

Date	2021-06-06
Pictures	14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-02-11
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #6		2024-02-07 11:46
MOT test	number	301427255784
Result		✓ Passed
Next expi	ry date	2025-02-11
Advice Nearside Rear Tyre worn close to legal limit/worn on edge And slightly perished outer sidewall. (5.2.3 (e))		
Advice	Under tray fitted.	

MOT #5	2024-02-06 15:23
MOT test number	665095112537
Result	X Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Under tray fitted.	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Rear Has metal shard in tread.	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge And slightly perish (5.2.3 (e))	ned outer sidewall.

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2023-02-03 12:27

MOT test number 937384961240

Result ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

Rear bush. (5.3.4 (a) (i))

Advice Nearside Rear Outer Tyre slightly damaged/cracking or perishing Sidewall. (5.2.3 (d) (ii))

Advice TPMS Light on.

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

Rear bush. (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge And slightly worn outer edge. (5.2.3

(e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2022-02-04 16:30

MOT test number 358246192718

Result

Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #2 2022-02-04 14:39

MOT test number 422922675229

Result ★ Failed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #1 2021-01-20 14:13

MOT test number 325062114107

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	11 February 2025
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full		TA

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-02-12
Last registration	2024-02-07
Complete history	See info



Registration #1	2018-02-12	15 mi
Registration #2	2021-01-20	38.818 mi
Registration #3		11.777 esi
Registration #4		11.777 es
Registration #5		11.777 esi
Registration #6		11.777 es
Registration #7		11.777 esi
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.117 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	77%
Pedestrian	76%
Safety systems	78%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	2640 mm
Length	4360 mm
Wheel base	2640 mm
Kerb weight	1420 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	43 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number 2ZRV628029