



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE TECH RUN DCI 86
Colour	Blue
Year of manufacture	2008
Top speed	108 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.900 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-08-15
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-06-20
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	34
Total items failed	19

MOT #22	2023-06-19 12:42
MOT test number	134920786345
Result	✓ Passed
Next expiry date	2024-06-20

MOT #21	2023-06-16 08:55
MOT test number	653246113070
Result	✗ Failed
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Steering rack has excessive free play detected at the steering wheel (steering rack fitted) N/S FRONT RACK EXCESS PLAY (2.3 (a) (i))

MOT #20	2022-06-15 14:59
MOT test number	392325974499
Result	✓ Passed
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened rusty inside (1.1.14 (a) (ii))

**MOT #19**

2022-06-15 13:03

**MOT test number**

817377965445

**Result**

✗ Failed

**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened rusty inside (1.1.14 (a) (ii))**Advice** Nearside Front Play in steering rack inner joint(s)**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Front Headlamp aim projected beam image is obviously incorrect both (4.1.2 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18**

2021-06-21 14:41

**MOT test number**

616055446124

**Result**

✓ Passed

**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #17**

2020-11-19 12:09

**MOT test number**

443587167704

**Result**

✓ Passed

**Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2020-11-18 11:07**MOT test number** 936296026205**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**MOT #15** 2019-11-11 14:43**MOT test number** 510836857399**Result** ✓ Passed**MOT #14** 2018-11-13 09:02**MOT test number** 906918993851**Result** ✓ Passed**MOT #13** 2018-11-13 09:02**MOT test number** 710795815315**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Windscreen washer not working (3.5 (a))**Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #12** 2017-11-14 15:53**MOT test number** 220661176821**Result** ✓ Passed**Advice** Service light on**Advice** Front tyres worn on inside edge and close to limit**MOT #11** 2017-11-14 15:53**MOT test number** 245191128001**Result** ✗ Failed**Advice** Service light on**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Front tyres worn on inside edge and close to limit**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #10** 2016-11-14 14:42**MOT test number** 680579761090**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2016-11-14 14:42**MOT test number** 263881683601**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #8** 2015-04-16 13:08**MOT test number** 499496005136**Result** ✓ Passed**MOT #7** 2014-04-22 12:54**MOT test number** 959622814136**Result** ✓ Passed**MOT #6** 2013-04-22 11:39**MOT test number** 219332713443**Result** ✓ Passed**MOT #5** 2012-04-13 11:58**MOT test number** 268634702420**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2011-04-21 14:29**MOT test number** 167411411174**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #3** 2011-04-19 16:36**MOT test number** 236319501163**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-04-18 15:50**MOT test number** 719658101185**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-04-14 11:54**MOT test number** 688134001157**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
20 June 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	20 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>CK08VKR</b>
Plate since	2019-09-28
Current registration	<b>CK08VKR</b>
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2008-04-14
Last registration	2023-06-19
Complete history	<a href="#">See info</a>



Registration #1	2008-04-14	8 mi
Registration #2	2011-04-14	25.168 mi
Registration #3	2011-04-18	25.246 mi
Registration #4	2011-04-19	25.284 mi
Registration #5	2011-04-21	25.336 mi
Registration #6	2012-04-13	32.401 mi
Registration #7	2013-04-22	38.782 mi
Registration #8	2014-04-22	45.599 mi
Registration #9	2015-04-16	51.890 mi
Registration #10	2016-11-14	63.178 mi
Registration #11	2016-11-14	63.178 mi
Registration #12	2017-11-14	67.606 mi
Registration #13	2018-05-22	71.277 mi
Registration #14	2018-05-22	71.277 mi
Registration #15	2018-05-22	71.277 mi
Registration #16	2018-05-22	71.277 mi
Registration #17	2018-05-22	71.277 mi
Registration #18	2018-05-22	71.277 mi
Registration #19	2018-05-22	71.277 mi
Registration #20	2018-05-22	71.277 mi
Registration #21	2018-05-22	71.277 mi
Registration #22	2018-05-22	71.277 mi
Registration #23	2018-05-22	71.277 mi
Registration #24	2018-05-22	71.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1458 mm
Length	4209 mm
Wheel base	2625 mm
Kerb weight	1195 kg
Max. allowed weight	17451 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D154928