



report date: 2024-03-28

General information

Make	MINI
Model	MINI JOHN COOPER WORKS
Colour	Black
Year of manufacture	2010
Top speed	148 mph
0 - 60 mph	6.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	211 BHP
Max. torque	260 Nm at 5.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-15
Pictures	13
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-08-04
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #12	2023-07-31 11:15
MOT test number	725522215753
Result	✓ Passed
Next expiry date	2024-08-04
Advice	Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11	2022-07-18 10:40
MOT test number	487181785184
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10	2021-08-05 13:38
MOT test number	121288927699
Result	✓ Passed

MOT #9	2020-11-09 11:04
MOT test number	842820843654
Result	✓ Passed
Advice	Rear tyres wearing uneven on inner edges

**MOT #8** 2019-11-12 13:04**MOT test number** 943432988022**Result** ✓ Passed**Advice** Rear tyres wearing slight uneven inner edge**MOT #7** 2018-09-26 13:41**MOT test number** 514924773196**Result** ✓ Passed**MOT #6** 2018-09-25 11:58**MOT test number** 538357517732**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))**Fail** Offside Front Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))**Advice** Nearside Front Upper Macpherson strut mounting damaged but not seriously weakened rubber mount (5.3.3 (b) (i))**MOT #5** 2017-10-05 11:50**MOT test number** 497544895856**Result** ✓ Passed**MOT #4** 2016-09-22 14:41**MOT test number** 700116858697**Result** ✓ Passed**Advice** Rear brake pads 4-5 mm /discs lipped-worn**MOT #3** 2015-10-08 08:40**MOT test number** 665023168713**Result** ✓ Passed**Advice** Oil leak



MOT #2	2014-10-14 10:38
MOT test number	227717884233
Result	✓ Passed

MOT #1	2013-10-18 14:58
MOT test number	645151093251
Result	✓ Passed

- Notice** Oil leak
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** O/s/r tyre worn on inner edge high and low spots



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
4 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	4 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	WR60NXX
Plate since	2019-09-28
Current registration	WR60NXX
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-11-08
Last registration	2023-07-31
Complete history	See info



Registration #1	2010-11-08	19 mi
Registration #2	2013-10-18	26.364 mi
Registration #3	2014-10-14	33.878 mi
Registration #4	2015-10-08	41.250 mi
Registration #5	2016-09-22	47.801 mi
Registration #6	2017-10-05	54.466 mi
Registration #7	2018-09-25	60.206 mi
Registration #8	2019-09-25	66.206 mi
Registration #9	2020-09-25	72.206 mi
Registration #10	2021-09-25	78.206 mi
Registration #11	2022-09-25	84.206 mi
Registration #12	2023-07-31	90.206 mi
Registration #13	2023-07-31	90.206 mi
Registration #14	2023-07-31	90.206 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number	B3811718
---------------	----------