



DGI3AYN

report date: 2024-03-28

General information

Make	MAZDA
Model	2 TS
Colour	White
Year of manufacture	2013
Top speed	104 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	119 Nm at 3.500 rpm
Engine capacity	1.349 cc
Cylinders	4
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-19
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-07
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	19
Total items failed	7

MOT #12	2024-03-08 16:24
MOT test number	439466821115
Result	✓ Passed
Next expiry date	2025-03-07
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Front brake discs lipped
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2024-03-08 16:24
MOT test number	540071328723
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front brake discs lipped
Pass with rectification	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Pass with rectification	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10** 2023-02-27 14:30**MOT test number** 385257409845**Result** ✓ Passed**Advice** Offside Front top mounting to shock noisy**Advice** Nearside Front Shock absorbers has slight external damage to the casing top cap insecure (5.3.2 (b))**Advice** Offside Front slightly distorted**MOT #9** 2023-02-24 15:54**MOT test number** 892803690968**Result** ✗ Failed**Advice** Nearside Front Shock absorbers has slight external damage to the casing top cap insecure (5.3.2 (b))**Advice** Offside Front top mounting to shock noisy**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front slightly distorted**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction phone holder stick to screen unable to remove (3.1 (a) (ii))**MOT #8** 2022-02-26 12:05**MOT test number** 683837826715**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #7** 2021-02-18 12:00**MOT test number** 951433171125**Result** ✓ Passed**Advice** Sill covers and under trays fitted

**MOT #6** 2020-02-18 13:36**MOT test number** 734048150833**Result** ✓ Passed**MOT #5** 2019-02-20 12:29**MOT test number** 121979035746**Result** ✓ Passed**Advice** Under trays fitted to vehicle**Advice** Unable to check rear seat belts due to dog cage.**MOT #4** 2018-02-21 11:17**MOT test number** 695935312849**Result** ✓ Passed**Advice** Nearside Front tyre cracking & has excessive wear on inner edge**Advice** Nearside Rear tyre cracking**Advice** Offside Front tyre cracking**MOT #3** 2017-02-24 10:21**MOT test number** 369245069932**Result** ✓ Passed**MOT #2** 2017-02-24 10:21**MOT test number** 941548053265**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #1** 2016-02-25 11:25**MOT test number** 413683509328**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
7 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	7 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-01
Last registration	2024-03-08
Complete history	See info



Registration #1	2013-03-01	11 mi
Registration #2	2016-02-25	12.813 mi
Registration #3	2017-02-24	17.714 mi
Registration #4	2017-02-24	17.714 mi
Registration #5	2018-02-21	23.575 mi
Registration #6	2019-02-20	28.571 mi
Registration #7	2020-02-18	32.893 mi
Registration #8	2021-02-17	35.277 mi
Registration #9	2021-02-17	35.277 mi
Registration #10	2021-02-17	35.277 mi
Registration #11	2021-02-17	35.277 mi
Registration #12	2021-02-17	35.277 mi
Registration #13	2021-02-17	35.277 mi
Registration #14	2024-03-08	35.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1030 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	ZJ B20946