



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D DRIVE R-DESIGN
Colour	Green
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-14
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-29
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	23
Total items failed	5

MOT #13	2024-01-18 16:20
MOT test number	848926770348
Result	✓ Passed
Next expiry date	2025-01-29
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Suspension arm corroded but not seriously weakened trailing arm bushes (5.3.3 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #12	2023-01-30 14:03
MOT test number	202985019020
Result	✓ Passed
Advice	Central Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11**

2023-01-25 09:05

MOT test number

777723811669

Result**✗ Failed****Advice** Central Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Rear Trailer electrical socket (13 pin) not operating the trailer lamps as intended (4.10 (c) (i))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #10**

2022-01-19 13:06

MOT test number

779375864516

Result**✓ Passed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2022-01-19 09:41

MOT test number

894126545662

Result**✗ Failed****Fail** Driver's door cannot be opened from inside the vehicle (6.2.3 (a))**Advice** Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8**

2021-01-11 16:25

MOT test number

886365481308

Result**✓ Passed**

**MOT #7** 2019-07-16 09:41**MOT test number** 412429191720**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-07-19 10:26**MOT test number** 741758539409**Result** ✓ Passed**MOT #5** 2017-07-14 09:18**MOT test number** 477535882182**Result** ✓ Passed**MOT #4** 2016-07-15 10:20**MOT test number** 672315538259**Result** ✓ Passed**MOT #3** 2015-07-22 13:01**MOT test number** 646093605256**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #2 2014-09-15 15:42

MOT test number 206228454225

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components

Notice Rear trailing arm front bushes slightly worn.

Notice Engine covers fitted obscuring some components in the engine bay

MOT #1 2013-09-09 09:14

MOT test number 528472853282

Result ✓ Passed

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
(2.4.G.2)

Notice Offside rear tyre slightly distorted on outer sidewall

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
(2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
29 January 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	29 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-24
Last registration	2024-01-18
Complete history	See info



Registration #1	2010-09-24	9 mi
Registration #2	2013-09-09	55.051 mi
Registration #3	2014-09-15	70.153 mi
Registration #4	2015-07-22	83.067 mi
Registration #5	2016-07-15	94.372 mi
Registration #6	2017-07-14	104.936 mi
Registration #7	2018-07-19	117.444 mi
Registration #8	2019-07-16	128.716 mi
Registration #9	2020-01-20	128.716 mi
Registration #10	2020-01-20	128.716 mi
Registration #11	2020-01-20	128.716 mi
Registration #12	2020-01-20	128.716 mi
Registration #13	2020-01-20	128.716 mi
Registration #14	2020-01-20	128.716 mi
Registration #15	2020-01-20	128.716 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	957553