



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-06-12
Pictures	32
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-31
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	9
Total items failed	17

MOT #12	2023-08-01 12:19
MOT test number	698549359578
Result	✓ Passed
Next expiry date	2024-07-31

MOT #11	2023-06-27 08:00
MOT test number	427603744788

Result	✗ Failed
--------	----------

- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #10**

2022-05-31 08:52

MOT test number

413534323006

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn on outer edge (5.2.3 (e))**Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))**MOT #9**

2022-05-30 10:01

MOT test number

200437082396

Result

✗ Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Worn on outer edge (5.2.3 (e))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #8**

2021-06-11 11:10

MOT test number

526478722830

Result

✓ Passed

**MOT #7** 2021-06-09 13:29**MOT test number** 470176486759**Result** ✗ Failed

- Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #6 2020-05-06 14:15**MOT test number** 350869115956**Result** ✓ Passed**MOT #5** 2019-03-27 13:57**MOT test number** 915372935307**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #4 2018-03-05 15:27**MOT test number** 501610048173**Result** ✓ Passed**MOT #3** 2017-03-23 16:45**MOT test number** 932722473256**Result** ✓ Passed

- Advice** Rear Tyre worn close to the legal limit both (4.1.E.1)

MOT #2 2016-03-30 15:07**MOT test number** 448911360477**Result** ✓ Passed



MOT #1		2016-03-30 15:07
MOT test number		831606907176
Result		✗ Failed
Pass with rectification	Offside Headlamp aim too high (1.8)	
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
31 July 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	YJ13SUP
Plate since	2019-03-29
Current registration	YJ13SUP
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-18
Last registration	2023-08-01
Complete history	See info



Registration #1	2013-03-18	16 mi
Registration #2	2016-03-30	46.145 mi
Registration #3	2016-03-30	46.145 mi
Registration #4	2017-03-23	50.152 mi
Registration #5	2018-03-05	62.977 mi
Registration #6	2019-03-27	80.126 mi
Registration #7	2020-05-06	84.873 mi
Registration #8	2020-05-06	84.873 mi
Registration #9	2020-05-06	84.873 mi
Registration #10	2020-05-06	84.873 mi
Registration #11	2020-05-06	84.873 mi
Registration #12	2020-05-06	84.873 mi
Registration #13	2020-05-06	84.873 mi
Registration #14	2020-05-06	84.873 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	227236K