





report date: 2024-03-29

General information

Make	LAND ROVER
Model	DISCOVERY SPORT TD4 HSE BLACK
Colour	Black
Year of manufacture	2018
Top speed	117 mph
0 - 100 km/h	8.9 seconds
0 - 60 mph	8.4 seconds
Gearbox	9 speed automatic

Engine & fuel consumption

Power	132 kW / 180 HP / 180 BHP
Max. torque	430 Nm at 1.750 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-08-03

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



YY67SVW

report date: 2024-03-29

MOT history

MOT expiry date	2024-07-28
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	3

MOT #6	2023-07-01 10:10
MOT test number	280169304797
Result	✓ Passed
Next expiry date	2024-07-28
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #5	2022-07-25 12:18
MOT test number	686412056220
Result	✓ Passed
MOT #4	2022-07-25 11:38
MOT test number	739358887219
Result	X Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	

CarCheck.co.uk page 3/11



Advice

YY67SVW

report date: 2024-03-29

MOT test number

Result

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2021-07-29 08:32 **MOT** test number 528141388404 Result × Failed **Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1

2020-10-03 09:57

MOT test number

338136618654

Result

Advice
Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

Advice
Front Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice
Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	28 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



YY67SVW

report date: 2024-03-29

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Damage 2

Type

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 6/11



YY67SVW

report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscory	
For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to	

HARMAN CO. C.	
	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	RIE SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-01-05
Last registration	2023-07-01
Complete history	See info



Registration #1	2018-01-05	20 mi
Registration #2	2020-10-03	38.308 mi
Registration #3	2021-07-29	46.517 mi
Registration #4	2021-07-29	46.517 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Adult	93%
Children	83%
Pedestrian	69%
Safety systems	82%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	2173 mm
Height	1724 mm
Length	4599 mm
Wheel base	2741 mm
Kerb weight	1845 kg
Max. allowed weight	2660 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	180226W0491204DTD

CarCheck.co.uk page 11/11