





### General information

Make	RENAULT
Model	ZOE DYNAMIQUE INTENS
Colour	White
Year of manufacture	2014
Top speed	84 mph
0 - 60 mph	13.5 seconds
Gearbox	1 speed automatic

### Engine & fuel consumption

Power	87 BHP
Max. torque	220 Nm at 2.500 rpm
Fuel type	Electricity







### Internet history

Entry 1

Date Pictures 2021-09-17

15

Listing price

View report









source: cargurus.co.uk



# MOT history

MOT expiry date	2024-08-07
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	13
Total items failed	5

<b>MOT #9</b> 2	023-08-08 09:17
MOT test number	861642847026
Result	🗸 Passed
Next expiry date	2024-08-07
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

МОТ #8	2023-08-08 07:20	
MOT test number	911568307262	
Result	× Failed	
<b>Fail</b> Offside Rear Direction indicator incorrect colour (4.4.3 (a))		
<b>Fail</b> Offside Windscreen wiper does not clear the windscreen effectively aero (3.4 (b) (ii))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	))	
Fail Nearside Windscreen wiper does not clear the windscreen of	effectively aero (3.4 (b) (ii))	





MOT #7		2022-10-03 09:16
MOT test i	number	354140770919
Result		✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge wearing badly on e	edges (5.2.3 (e))
Advice	Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Rear Nail in tyre Multiple nails in tyre	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #6	2022-09-30 11:13
MOT test number	978413952000
Result	🗙 Failed
<b>Advice</b> Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
FailNearside Front Upper Anti-roll bar linkage ball joint dust cover no longer(5.3.4 (b) (ii))	prevents the ingress of dirt
Advice Offside Front Tyre worn close to legal limit/worn on edge wearing bac	dly on edges (5.2.3 (e))
Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Nearside Rear Nail in tyre Multiple nails in tyre	
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #5	2021-09-29 10:31
MOT test number	460348934007
Result	✓ Passed
MOT #4	2020-09-25 08:52
MOT test number	816596324464

Result

🗸 Passed






MOT #3	2019-09-17 10:03
MOT test number	252146492971
Result	✓ Passed
Advice Rear Tyre slightly damaged/cracking or perishing both rear tyres crac (ii))	cking worn to 4mm (5.2.3 (d)
MOT #2	2018-09-07 09:20
MOT test number	468443362329
Result	✓ Passed
MOT #1	2017-09-26 09:32
MOT test number	457284094900
Result	✓ Passed



Tax & MOT check







#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE D
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	 
Category	 AMPL
Туре	

#### Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
**********	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-10-31
Last registration	2023-08-08
Complete history	See info



Registration #1	2014-10-31	20 mi
Registration #2	2017-09-26	17.046 mi
Registration #3	2018-09-07	20.916 mi
Registration #4	2019-09-17	26.069 mi
Registration #5	2020-09-25	29.696 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi





### Car features

S0225	Air conditioning	
\$0295		
50482		
50501		
50566		
\$0567		
50569		

# Safety ratings

NCAP rating	****
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



Dimensions & weight	
Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1468 kg
Max. allowed weight	1943 kg
Additional information	
Fuel delivery	Not Applicable
Number of doors	5

Number of doors	5	
Number of seats	5	
Number of axles CarCheck.co.uk	2	page 12/12

**Engine number** 

A052872