

Ford



General information

| Make | FORD |
|---------------------|----------------|
| Model | MONDEO ZETEC |
| Colour | Silver |
| Year of manufacture | 2010 |
| Top speed | 130 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 144 BHP | 0 < 101 A |
|-------------------------|---------------------|-------------------------------------|
| Max. torque | 190 Nm at 4.500 rpm | 101 - 120 ^B _C |
| Engine capacity | 1.999 cc | 121 - 140 P |
| Cylinders | 4 | 141 - 165 |
| Fuel type | Petrol | 166 - 185 |
| Consumption city | 25.2 mpg | 186 - 225 |
| Consumption extra urban | 47.1 mpg | 225+ |
| Consumption combined | 35.8 mpg | |
| CO2 emission | 184 g/km | |
| CO2 label | I | |







Internet history

Entry 1

Date

Pictures

2021-11-07

33

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-11-24 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 12 |
| Failed MOT tests | 0 |
| Total advice items | 5 |
| Total items failed | 0 |

| MOT #12 | 2023-11-01 13:27 |
|------------------|------------------|
| MOT test number | 216696028640 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-24 |

| MOT #11 | | 2022-11-09 15:23 |
|----------|--|------------------|
| MOT test | number | 595582711458 |
| Result | | Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #10 | 2021-11-25 12:32 |
|-----------------|------------------|
| MOT test number | 694632949567 |
| Result | ✓ Passed |
| | |
| MOT #0 | 2021 02 27 11.24 |

| MOT #9 | 2021-02-27 11:24 |
|-----------------|------------------|
| MOT test number | 469297273474 |
| Result | ✓ Passed |

| MOT #8 | 2020-04-02 10:55 |
|-----------------|------------------|
| MOT test number | 689141088166 |
| Result | ✓ Passed |





| MOT #7 | 2019-08-05 12:03 | |
|--|------------------|--|
| MOT test number | 700322512099 | |
| Result | ✓ Passed | |
| | | |
| MOT #6 | 2018-08-15 08:20 | |
| MOT test number | 394251136668 | |
| Result | ✓ Passed | |
| Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) | | |
| | | |
| MOT #5 | 2017-08-16 07:52 | |
| MOT test number | 544489119458 | |
| Result | ✓ Passed | |

| MOT #4 | | 2016-08-22 09:48 |
|----------|---|------------------|
| MOT test | number | 356572918008 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #3 | 2015-08-18 08:28 |
|---------------------------|------------------|
| MOT test number | 668740935239 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2014-08-18 12:33 |
| | |
| MOT test number | 826630934283 |
| MOT test number Result | 826630934283 |

| MOT #1 | 2013-08-19 15:28 |
|-----------------|------------------|
| MOT test number | 916141533232 |
| Result | ✓ Passed |



Tax & MOT check

| √ Taxed | ✓ МОТ |
|-------------------------|-------------------------------------|
| Tax due: 1 June 2024 | Expires: 24 November 2024 |
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 24 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------------|
| Date | FER I |
| Category | A PLANE |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E Stand |
| Date | * |
| Category | ante. |
| Туре | |

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2010-09-03 |
| Last registration | 2023-11-01 |
| Complete history | See info |



| Registration #1 | 2010-09-03 | 20 mi |
|--------------------------------------|------------|--|
| Registration #2 | 2013-08-19 | 12.207 mi |
| Registration #3 | 2014-08-18 | 15.179 mi |
| Registration #4 | 2015-08-18 | 18.721 mi |
| Registration #5 | 2016-08-22 | 22.372 mi |
| Registration #6 | 2017-08-16 | 24.648 mi |
| Registration #7 | 2018-08-15 | 27.205 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | |
| | | |
| Registration #10 | | 11.227 es |
| Registration #10 Registration #11 | | 11.117 es |
| - | | 11.117 est 11.117 est 11.117 est |
| Registration #11 | | 0.000 est 0.000 est 0.000 est 0.000 est |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 2078 mm |
| Height | 1451 mm |
| Length | 4778 mm |
| Wheel base | 2850 mm |
| Kerb weight | 1479 kg |
| Max. allowed weight | 2090 kg |
| Additional information | |
| Fuel tank capacity | 70 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | AU29577 |