



HYUNDAI

E0I4DYS

report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI ACTIVE BLUE DRIVE
Colour	Silver
Year of manufacture	2014
Top speed	125 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-07-03
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-22
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	9
Total items failed	11

MOT #10	2023-06-23 13:07
MOT test number	355967133303
Result	✓ Passed
Next expiry date	2024-06-22

MOT #9	2022-06-14 13:47
MOT test number	200779729768
Result	✓ Passed

MOT #8	2021-06-01 15:30
MOT test number	704904991432
Result	✓ Passed

MOT #7	2020-06-02 15:50
MOT test number	481532697083
Result	✓ Passed

MOT #6	2020-06-02 11:39
MOT test number	486151327339
Result	✗ Failed
Fail	Offside Headlamp not working on main beam (4.1.1 (a) (ii))

**MOT #5** 2019-03-30 10:22**MOT test number** 331496446840**Result** ✓ Passed**Advice** Front brake pads worn low**Advice** Offside front nearside front offside rear tyres worn bold on edges 3mm 205-60-16**MOT #4** 2018-03-23 13:32**MOT test number** 792029765478**Result** ✓ Passed**MOT #3** 2018-03-23 09:16**MOT test number** 920596418783**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Tyre HEAVILY worn on inner and outer edges.**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn HEAVILY on inner and outer edges.**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2017-04-01 12:47**MOT test number** 231156198671**Result** ✓ Passed**Advice** Front bumper cracked o/s



MOT #12017-04-01 09:36

MOT test number196383922126

Result

Failed

Advice

Offside Front Tyre worn close to the legal limit worn on outer edge (4.1.E.1)

Fail

Nearside rear parking brake recording little or no effort (3.7.B.6a)

Advice

Front bumper cracked o/s

Fail

Offside Front Seat belt locking mechanism does not secure or release does not release correctly (5.2.5a)

Fail

Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice

Offside Front Tyre worn close to the legal limit worn almost to cord on inner edge (4.1.E.1)

Advice

Offside Front Tyre worn close to the legal limit central tread (4.1.E.1)

Fail

Offside rear parking brake recording little or no effort (3.7.B.6a)

Fail

Parking brake: efficiency below requirements (3.7.B.7)

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
22 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-04-09
Last registration	2023-06-23
Complete history	See info



Registration #1	2014-04-09	11 mi
Registration #2	2017-04-01	40.902 mi
Registration #3	2017-04-01	40.902 mi
Registration #4	2018-03-23	59.597 mi
Registration #5	2018-03-23	59.597 mi
Registration #6	2019-03-30	78.594 mi
Registration #7	2019-03-30	78.597 mi
Registration #8	2019-03-30	78.597 mi
Registration #9	2019-03-30	78.597 mi
Registration #10	2019-03-30	78.597 mi
Registration #11	2019-03-30	78.597 mi
Registration #12	2019-03-30	78.597 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1610 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	D4FDDU368720