





report date: 2024-03-29

#### General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Blue
Year of manufacture	2014
Top speed	120 mph
0 - 100 km/h	10.9 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/13



# Internet history

#### Entry 1

Date 2021-07-13

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-09-10
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	12
Total items failed	10

MOT #12	2023-09-11 08:52
MOT test number	421760721507
Result	✓ Passed
Next expiry date	2024-09-10
Advice Osf bumper damage no sharp edges and still secure	

MOT #11	2022-07-27 17:22
MOT test number	915028607956
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2022-07-26 11:05	
MOT test number	539738201341	
Result	<b>X</b> Failed	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Nearside Rear Lower Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))		
Fail Offside Rear Lower Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))		

CarCheck.co.uk page 3/13



MOT #9 2021-07-19 15:55

MOT test number 272657457513

Result \rightarrow Passed

Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**Advice** Central Rear Seat belt buckle slightly damaged (7.1.2 (d))

**MOT #8** 2021-07-19 15:55

**MOT test number** 67339999873

**Result** X Failed

Pass with rectification Nearside Front Headlamp aim projected beam image is obviously incorrect

(4.1.2 (c))

Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Central Rear Seat belt buckle slightly damaged (7.1.2 (d))

MOT #7 2021-04-29 13:29

MOT test number 573432007834

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge only just met requirements (5.2.3 (e))

CarCheck.co.uk page 4/13



MOT #6 2021-04-24 07:38

**MOT test number** 711615130809

Result X Failed

**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge only just met requirements (5.2.3 (e))

**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #5** 2020-02-13 15:34

**MOT test number** 498829106085

**Result** 
✓ Passed

MOT #4 2019-02-23 11:14

**MOT test number** 284502892668

Result \( \sqrt{Passed} \)

MOT #3 2018-02-27 11:00

**MOT test number** 859482307640

Result 

Passed

MOT #2 2018-02-27 11:00

MOT test number 557394485631

Result X Failed

**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)

**Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 5/13



MOT #1

MOT test number

438532112599

Result

Advice Engine cover and under tray fitted

CarCheck.co.uk page 6/13





#### Tax & MOT check





Expires: 10 September 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	10 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
***************************************	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NIK NIK
Plate since	
Current registration	AK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-04-30
Last registration	2023-09-11
Complete history	See info



Registration #1	2014-04-30	27 mi
Registration #2	2017-02-28	33.440 mi
Registration #3	2018-02-27	42.074 mi
Registration #4	2018-02-27	42.074 mi
Registration #5	2019-02-23	50.603 mi
Registration #6	2020-02-13	53.938 mi
Registration #7	2021-04-24	76.166 mi
Registration #8		7.77
Registration #9		77.777 46
Registration #10		7.77
Registration #11		77.777 46
Registration #12		77,777 46
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1688 kg
Max. allowed weight	2505 kg

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles2Engine numberET47075