





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	Silver
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	Е



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1


Date 2021-10-31


Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-09
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	17
Total items failed	2

MOT #11	2023-11-02 12:02
MOT test number	316631371782
Result	✓ Passed
Next expiry date	2024-11-09

MOT #10	2022-11-10 15:05
MOT test	number 190197092723
Result	✓ Passed
Advice	Tyre worn close to legal limit/worn on edge both rear tyre worn on inner edges (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9	2021-10-26 15:21
MOT test number	554299218346
Result	✓ Passed

MOT #8	2020-11-06 14:30
MOT test number	161479735755
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2019-10-24 11:30 MOT test number 812274854999

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened scored on disc surface (1.1.14 (a) (ii))

MOT #6 2019-10-24 09:12

MOT test number 192272349915

Result × Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened scored on disc surface (1.1.14 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #5 2018-11-09 11:34

MOT test number 589160123786

Result
✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened n/s and o/s worn (1.1.14 (a) (ii))

Advice Nearside Front Anti-roll bar linkage damaged but not seriously weakened dust cover split top of linkage (5.3.3 (b) (i))

Advice No emission detected time of test body trays fitted can not check some parts

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4		2017-11-10 12:21
MOT test	number	827286070118
Result		✓ Passed
Advice	Both front tyres worn on inner edges	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened	(3.5.1i)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3	3.5.1i)

MOT #3		2016-11-30 11:10
MOT test n	umber	271905993030
Result		✓ Passed
MOT #2		2015-11-28 13:47
MOT test n	umber	206377483778
Result		✓ Passed
MOT #1		2014-11-17 11:10
MOT test n	umber	416161824339
Result		✓ Passed
Notice	Rear seat belts not checked due to child seats	
Notice	Nail in offside rear tyre	
Notice	Underside covered making inspection difficult	

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check





Expires: 9 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	9 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates. mber of plates -More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-12-14
Last registration	2023-11-02
Complete history	See info



Registration #1	2011-12-14	27 mi
Registration #2	2014-11-17	18.682 mi
Registration #3	2015-11-28	26.811 mi
Registration #4	2016-11-30	36.323 mi
Registration #5	2017-11-10	44.028 mi
Registration #6	2018-11-09	51.240 mi
Registration #7	2019-10-24	59.246 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

More info >

CarCheck.co.uk page 11/12



FP61UEU report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

CarCheck.co.uk page 12/12

Number of axles	2

Engine number CAY 586764