





report date: 2024-03-28

General information

Make	TOYOTA	
Model	VERSO VALVEMATIC DESIGN	
Colour	Bronze	
Year of manufacture	2016	
Top speed	115 mph	
0 - 60 mph	11.1 seconds	
Gearbox	7 speed CVT	

Engine & fuel consumption

Power	147 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



LP16YSY

report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-28

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-17
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	23
Total items failed	3

MOT #8		2023-07-17 15:01
MOT test	number	931636401362
Result		✓ Passed
Next expi	ry date	2024-07-17
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7		2023-07-17 11:23
MOT test	number	108469056005
Result		X Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Rear fog lamp not working (4.5.1 (a) (ii))	

MOT #6	2022-07-18 13:51
MOT test number	766325850262
Result	✓ Passed
Advice Nearside Front Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



MOT #5 2021-07-07 12:50

MOT test number 764426711228

MOT #4 2021-07-07 12:50

MOT test number 383364677160

Result X Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4

Pass with rectification Offside Rear Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #3 2020-09-21 16:01

MOT test number 784012215257

Result ✓ Passed

Advice Nearside Front Brake pad(s) wearing thin close! (1.1.13 (a) (ii))

Advice Undertrays fitted

Advice Offside Front Brake pad(s) wearing thin BORDERLINE, STRONG ADVISE! (1.1.13 (a) (ii))

Minor Offside Rear Stop lamp(s) lens defective which has no effect on emitted light damaged (4.3.1 (b)

(i))

(b) (ii))

Advice Front Brake disc worn, but not excessively lipped, both sides (1.1.14 (a) (i))

Advice Nearside Rear bumper damaged

CarCheck.co.uk page 4/12



MOT #2 2020-09-21 14:56

MOT test number 536466985710

Result X Failed

Advice Nearside Front Brake pad(s) wearing thin close! (1.1.13 (a) (ii))

Minor Offside Rear Stop lamp(s) lens defective which has no effect on emitted light damaged (4.3.1 (b) (i))

Advice Front Brake disc worn, but not excessively lipped, both sides (1.1.14 (a) (i))

Advice Undertrays fitted

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm worn down to expose cords (5.2.3 (e))

Advice Offside Front Brake pad(s) wearing thin BORDERLINE, STRONG ADVISE! (1.1.13 (a) (ii))

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords damaged outer sidewall, cords visible (5.2.3 (d) (i))

Advice Nearside Rear bumper damaged

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm tread (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2mm tread (5.2.3 (e))

MOT #1 2019-03-23 11:08

MOT test number 468411428099

Result

Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	17 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Venicle class	40
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



LP16YSY

report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full research	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	NIE NIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-06-29
Last registration	2023-07-17
Complete history	See info



Registration #1	2016-06-29	19 mi
Registration #2	2019-03-23	9.088 mi
Registration #3	2020-09-21	21.484 mi
Registration #4	2020-09-21	21.484 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		77.777 es
Registration #9		11.117 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4460 mm
Wheel base	2780 mm
Kerb weight	1540 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Engine number

2ZRV405495