





report date: 2024-03-29

General information

Make	FIAT
Model	PANDA TWINAIR
Colour	Turquoise
Year of manufacture	2014
Top speed	103 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 3

Date	2024-02-05

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 2

Date	2021-07-07
Pictures	20

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-07-01
Pictures	20

Listing price <u>View report</u>









source: heycar.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-31
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	11
Total items failed	3

MOT #11	2023-11-01 14:48
MOT test number	914019974428
Result	✓ Passed
Next expiry date	2024-10-31

N	1OT #10	2023-11-01 14:48
N	10T test number	128224374296
F	Result	X Failed
	Pass with rectification	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps
	both (4.7.1 (b) (ii))	

MOT #9	2022-10-24 14:33
MOT test number	549510068318
Result	✓ Passed

MOT #8	2021-10-26 15:43
MOT test number	726335293897
Result	✓ Passed

MOT #7	2021-01-13 15:22
MOT test number	903847969788
Result	✓ Passed
Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice Front shocks damp

Advice Exhaust corroded

MOT #5

MOT test number

917066192162

Result

Advice Light oil residue both front shock absorbers

MOT test number

Result

Advice Light oil residue both front shock absorbers

Fail Offside Side repeater not working (4.4.1 (a) (ii))

Advice Lip and corrosion to rear brake discs, inner pads appear worn low

MOT #3

MOT test number

403437878350

Result

Advice Offside front tyre worn to 3mm

Advice Nearside front tyre worn close to legal limit

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

268422787369

Result

Advice Offside front tyre worn to 3mm

Fail Nearside Headlamp aim too low (1.8)

Advice Slight lip and corrosion front brake discs, pads approx. 70% worn

Advice Nearside front tyre worn close to legal limit

MOT #1	2017-01-20 09:43
MOT test number	762100061038
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax expired: 10 November 2023



Expires: 31 October 2024

Tax status	Expired at 10 November 2023
Days left	171 days too late
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	la : a b a
UWNEr	INISTARV
OWITCH	IIISCOLY

Sime misery	
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report \(\frac{1}{2} \)	

THE STREET STREET, STR	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	OK SIZ
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-01-27
Last registration	2023-11-01
Complete history	See info



Registration #1	2014-01-27	27 mi
Registration #2	2017-01-20	30.369 mi
Registration #3	2018-01-09	41.896 mi
Registration #4	2018-01-09	41.896 mi
Registration #5	2019-01-17	52.484 mi
Registration #6	2019-01-17	52.485 mi
Registration #7	2020-01-25	59.365 mi
Registration #8	2021-01-13	64.311 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1672 mm
Height	1605 mm
Length	3686 mm
Wheel base	2305 mm
Kerb weight	1125 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2
Engine number 0221746