



report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Blue
Year of manufacture	2006
Top speed	137 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	152 BHP
Max. torque	366 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 2

Date	2021-08-02
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-21
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-02-02
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	51
Total items failed	8

MOT #17	2023-02-03 11:04
MOT test number	746146976608
Result	✓ Passed
Next expiry date	2024-02-02
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16	2022-01-26 15:32
MOT test number	990724998904
Result	✓ Passed
Advice	Rear corrosion throughout suspension components and sills
Advice	Front Service brake fluctuating, but not excessively both (1.2.1 (e))
Advice	Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))

**MOT #15**

2022-01-20 14:49

**MOT test number**

385867632147

**Result****✗ Failed****Advice** Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))**Fail** Offside Rear Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))**Advice** Rear corrosion throughout suspension components and sills**Fail** Brake pipe excessively corroded mainruns front to rear (1.1.11 (c))**Advice** Front Service brake fluctuating, but not excessively both (1.2.1 (e))**MOT #14**

2021-01-12 14:15

**MOT test number**

947919799802

**Result****✓ Passed****Advice** Nearside Play in steering rack inner joint(s)**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))**Advice** Brake pipe corroded, covered in grease or other material both front to rear pipes. (1.1.11 (c))**MOT #13**

2021-01-12 09:06

**MOT test number**

571860502646

**Result****✗ Failed****Advice** Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Brake pipe corroded, covered in grease or other material both front to rear pipes. (1.1.11 (c))**Advice** Nearside Play in steering rack inner joint(s)**Fail** Offside Rear Suspension arm pin or bush excessively worn toe in control arm. Marked in yellow. (5.3.4 (a) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #12**

2019-07-08 12:30

**MOT test number**

472275536898

**Result**

✓ Passed

**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement inner bush of forward lower arm. (5.3.4 (a) (i))**MOT #11**

2018-07-05 08:52

**MOT test number**

438774829635

**Result**

✓ Passed

**Advice** Brake pipe corroded, covered in grease or other material front to nearside rear pipe, along floor pan. (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides of car (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin inner pads, both sides of car. (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear tyre showing uneven wear.**MOT #10**

2017-07-11 13:30

**MOT test number**

670745706804

**Result**

✓ Passed

**Advice** Front Tyre worn close to the legal limit both sides of car (4.1.E.1)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)



<b>MOT #9</b>	2016-06-27 13:51
<b>MOT test number</b>	759387872833
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
<b>Advice</b>	Rear Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement both sides of car (2.4.G.2)

<b>MOT #8</b>	2015-07-07 14:54
<b>MOT test number</b>	235878085196
<b>Result</b>	✓ Passed
<b>Notice</b>	N/s/r drop link bar slight play detected
<b>Notice</b>	O/s/r roll bar d bush worn BORDERLINE
<b>Notice</b>	O/s/f brake disc inner face corroded
<b>Notice</b>	N/s/f inner brake pad looks lower than the rest

<b>MOT #7</b>	2015-07-06 09:13
<b>MOT test number</b>	527247785180
<b>Result</b>	✗ Failed
<b>Notice</b>	N/s/r drop link bar slight play detected
<b>Fail</b>	Offside Rear Brake pipe excessively corroded (3.6.B.2c)
<b>Notice</b>	O/s/r roll bar d bush worn BORDERLINE
<b>Fail</b>	Offside Inner Rear Tie bar/rod has excessive play in a pin/bush (2.4.G.2)
<b>Notice</b>	O/s/f brake disc inner face corroded
<b>Fail</b>	Offside Front coil spring broken (2.4.C.1a)
<b>Notice</b>	N/s/f inner brake pad looks lower than the rest
<b>Fail</b>	Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

**MOT #6** 2014-07-14 11:22**MOT test number** 758465994191**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2013-06-24 15:34**MOT test number** 248135073135**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2012-07-23 10:32**MOT test number** 979375702221**Result** ✓ Passed**MOT #3** 2011-06-24 10:34**MOT test number** 399755671194**Result** ✓ Passed**Notice** Nail in o/s/r tyre (repairable)**Notice** Glow plug light on**MOT #2** 2010-07-01 11:53**MOT test number** 450602380170**Result** ✓ Passed



MOT #12009-07-10 10:40

MOT test number643821199184

Result		✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Nail in nearside rear tyre	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nail in offside rear tyre	



Tax & MOT check

X

Untaxed

Tax expired:  
22 September 2023

X

MOT

Expired:  
2 February 2024

Tax status	Expired at 22 September
Days left	219 days too late
MOT expiry date	2 February 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>LA06YFJ</b>
Plate since	2024-03-28
Current registration	<b>LA06YFJ</b>
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-07-13
Last registration	2023-02-03
Complete history	<a href="#">See info</a>



Registration #1	2006-07-13	16 mi
Registration #2	2009-07-10	30.675 mi
Registration #3	2010-07-01	43.790 mi
Registration #4	2011-06-24	61.742 mi
Registration #5	2012-07-23	69.016 mi
Registration #6	2013-06-24	74.953 mi
Registration #7	2014-07-14	82.043 mi
Registration #8	2015-07-06	88.465 mi
Registration #9	2015-07-07	88.479 mi
Registration #10	2016-06-27	95.585 mi
Registration #11	2016-06-27	95.585 mi
Registration #12	2016-06-27	95.585 mi
Registration #13	2016-06-27	95.585 mi
Registration #14	2016-06-27	95.585 mi
Registration #15	2016-06-27	95.585 mi
Registration #16	2016-06-27	95.585 mi
Registration #17	2016-06-27	95.585 mi
Registration #18	2016-06-27	95.585 mi
Registration #19	2016-06-27	95.585 mi
Registration #20	2016-06-27	95.585 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	060407132209BG