



 **X4IIE****NJ**

report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD VTEC S
Colour	Red
Year of manufacture	2000
Top speed	127 mph
0 - 60 mph	10.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	175 Nm at 4.800 rpm
Engine capacity	1.850 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	40.4 mpg
Consumption combined	33.2 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2021-02-06
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	22
Total items failed	1

MOT #16	2020-02-07 11:32
MOT test number	901023766725
Result	✓ Passed
Next expiry date	2021-02-06

MOT #15	2019-05-09 11:51
MOT test number	309142650374
Result	✓ Passed

MOT #14	2018-05-30 10:33
MOT test number	612819167645
Result	✓ Passed

MOT #13	2017-05-19 11:28
MOT test number	278040580697
Result	✓ Passed

MOT #12	2016-05-25 10:56
MOT test number	674931303859
Result	✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2015-05-18 13:23**MOT test number** 985978335122**Result** ✓ Passed**MOT #10** 2014-05-21 13:00**MOT test number** 476011144170**Result** ✓ Passed**MOT #9** 2014-05-19 12:30**MOT test number** 489819934160**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2013-05-28 17:22**MOT test number** 597118843105**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Side repeater slightly discoloured (1.4.A.2f)

**MOT #7** 2012-04-23 12:36**MOT test number** 966274512129**Result** ✓ Passed**Advice** Nearside Front Upper Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Front Upper Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Notice** Silencer to mid pipe joint corroded**MOT #6** 2011-01-12 12:21**MOT test number** 515342211093**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2010-01-22 14:44**MOT test number** 301622820017**Result** ✓ Passed**Advice** Offside Headlamp not in good working order but not adversely affecting beam image (1.2.4a)**Notice** Rear bumper bracket corroding**Advice** Nearside Headlamp not in good working order but not adversely affecting beam image (1.2.4a)**MOT #4** 2009-01-19 17:16**MOT test number** 902069219011**Result** ✓ Passed**Advice** Vehicle structure has slight corrosion (6.1.A.1)**MOT #3** 2008-01-21 14:45**MOT test number** 523111028009**Result** ✓ Passed



MOT #2 2007-01-08 12:53

MOT test number 953458507033

Result ✓ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2006-01-16 15:34

MOT test number 153796516425

Result ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
22 December 2020

✕
MOT

Expired:
6 February 2021

Tax status	Expired at 22 December 2020
Days left	1223 days too late
MOT expiry date	6 February 2021
Full MOT history	See MOT history



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2000-09-27
Last registration	2020-02-07
Complete history	See info



Registration #1	2000-09-27	16 mi
Registration #2	2006-01-16	37.022 mi
Registration #3	2007-01-08	41.746 mi
Registration #4	2008-01-21	45.636 mi
Registration #5	2009-01-19	49.161 mi
Registration #6	2010-01-22	52.255 mi
Registration #7	2011-01-12	55.222 mi
Registration #8	2012-04-23	59.574 mi
Registration #9	2013-05-28	63.202 mi
Registration #10	2014-05-28	65.277 mi
Registration #11	2015-05-28	67.352 mi
Registration #12	2016-05-28	69.427 mi
Registration #13	2017-05-28	71.502 mi
Registration #14	2018-05-28	73.577 mi
Registration #15	2019-05-28	75.652 mi
Registration #16	2020-02-07	77.727 mi
Registration #17	2020-02-07	79.802 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1750 mm
Height	1430 mm
Length	4595 mm
Kerb weight	1380 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	F18B2E124888